1/13/25, 9:18 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24100459/AVP3M4

Date: 13/01/2025

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle No:

SNG3238J

Insured Vehicle No:

GBA2457Z

Chassis No:

Odometer:

Date of Loss:

16/10/2024

Nature of Claim:

TP

Claim No:

CHZC26193

52033 km

WAUZZZ8V2K1013778

DMCV2400224H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

SNG3238J Reg No:

Make & Model: AUDI A3, 1.0 TFSI (A) Engine No:

Reg. Date: 29/01/2019 (Man. Year: 2018)

Grey

Engine Capacity: Market Value/New Car 999 cc N/A

Price:

Colour:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Front Left Side: Rear Left Side: Continental 6 mm Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,579.00	10,824.20	2,754.80	20.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,530.00	1,400.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,509.00	15,354.20	4,154.80	21.30
+ GST 9.00/9.00% (S\$)	1,755.81	1,381.88	373.93	21.30
Nett Amount (S\$)	21,264.81	16,736.08	4,528.73	21.30

INSPECTION

Date of Assignment: 25/10/2024

PREMIUM AUTOMOBILES PTE LTD (UBI) Date Inspected: 29/10/2024 Inspected At:

55 UBI ROAD 1

SINGAPORE 408699

Estimated Period of Repair: 4.0 days

ADRIAN LING VERON CHEN Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2025)

Parts: 143 AUDI A3 1.0 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNG3238J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,736.00 FS	*2,736.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	209.00 FS	*-FS
3	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	49.00 FS	*-FS
4	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	645.00 FS	*-FS
5	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	357.00 FS	*-FS
6	1		*FRONT BUMPER TRIM COVER LH	Not Necessary	204.00 FS	*-FS
7	1		*WHEEL HOUSING LINERS ADAPTERS LH	Not Necessary	48.00 FS	*-FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	236.00 FS	*-FS
9	1		*LED HEADLIGHT	Cut	6,647.00 FS	*6,647.00 FS
10	1		*LED HEADLIGHT LIFT CYLINDER LH	Not Necessary	170.00 FS	*-FS
11	1		*LED HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	86.00 FS	*-FS
12	1		*FRONT FENDER LH	Distorted	1,016.00 FS	*1,016.00 FS
13	1		*FRONT FENDER ATTACHEMENTS PARTS	Not Necessary	85.00 FS	*-FS
14	1		*FRONT FENDER BRACKET LOWER LH	Not Necessary	45.00 FS	*-FS
15	1		*FRONT FENDER BRACKET UPPER LH	Bent	72.00 FS	*71.60 FS
16	1		*FRONT FENDER BRACE	Bent	122.00 FS	*121.50 FS
17	1		*FRONT WHEEL HOUSING LINER SEAL LH	Not Necessary	43.00 FS	*-FS
18	1		*FRONT WHEEL HOUSING LINER LH	Deformed	204.00 FS	*203.50 FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENTS PARTS	Not Necessary	105.00 FS	*-FS
20	1		*SUNDRIES	Necessary	500.00 FS	*28.60 FS
F=Fra	anchise	part. S=Spc	Nett.		-	

Total Parts (S\$) 13,579.00 10,824.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New New	3,150.00	2,250.00
2	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,300.00	1,800.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	480.00
	Gross Labo	5,930.00	4,530.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >