

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100460/KNP3E2
Date: 11/11/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003932659
Claimant Vehicle No :	SJJ203K	Insured Vehicle No :	SNL8278J
Date of Loss:	21/10/2024	Nature of Claim:	TP
		Claim No:	377934

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ203K		
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 COMFORTLINE 280 TSI EQPc (A)	Engine No:	CZE546289
Reg. Date:	28/02/2018 (Man. Year: 2017)	Chassis No:	WVGZZZ5NZJW848418
Colour:	White	Odometer:	101687 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,649.48	8,056.81	592.67	6.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,580.00	950.00	37.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,179.48	9,636.81	1,542.67	13.80
Approved Total (Overridden) (S\$)		7,650.00		
Nett Amount (S\$)	11,179.48	7,650.00	3,529.48	31.57

INSPECTION

Date of Assignment:	28/10/2024		
Date Inspected:	28/10/2024	Inspected At:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2024)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 COMFORTLINE 280 TSI EQPc (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ203K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Buckled / Dented	1,171.80 FL	*1,171.80 FL
2	1		*REAR BUMPER BOTTOM (BLACK)	Dented / Cut	434.05 FL	*434.05 FL
3	1		*REAR BUMPER BOTTOM (BLACK) LH REFLECTOR LONG	Cracked	96.00 FL	*96.00 FL
4	1		*REAR BUMPER BOTTOM (BLACK) LH REFLECTOR SHORT	Cracked	81.00 FL	*81.00 FL
5	1		*REAR BUMPER REVERSE SENSOR (3PCS)	Shorted/Dented(2Pcs Only)	865.50 FL	*577.00 FL
6	1		*REAR BUMPER LH SIDE RETAINER	Serviceable	76.75 FL	*- FL
7	1		*REAR BUMPER INNER FOAM	No such part	96.75 FL	*- FL
8	1		*REAR BUMPER INNER REINFORCEMENT	Bent	925.95 FL	*925.95 FL
9	1		*LH TAILLAMP	Cut	584.15 FL	*584.15 FL
10	1		*REAR TAILGATE	Bent	2,728.05 FL	*2,728.05 FL
11	1		*REAR TAILGATE LH TIGUAN EMBLEM	Necessary	130.80 FL	*130.80 FL
12	1		*REAR TAILGATE LH SIDE LAMP	Cut	540.85 FL	*540.85 FL
13	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*REAR TAILGATE WEATHERSTRIP (\$182.15) (50%)	Distorted / Dented	163.94 FS	*91.07 FS
15	1		*REAR TAILGATE TOP LOCK	Dented	274.15 FL	*274.15 FL
16	1		*REAR END PANEL	Bent	1,229.25 FL	*1,229.25 FL
17	1		*SET REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
18	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,578.99	8,934.12
- List Item Discount on L Items 10.00/10.00% (\$)	929.51	877.31
Total Parts (\$)	8,649.48	8,056.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	1,000.00	600.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	50.00	20.00
4	TO REMOVE, REFIT REAR WINDSCREEN	New	140.00	120.00
5	TO REMOVE, REFIT REAR TAILGATE FITTINGS	New	80.00	60.00
6	TO REMOVE, REFIT & RESET REVERSE SENSORS	New	80.00	60.00
7	TO REMOVE, REFIT REAR UPHOLSTERY & ATTACHMENTS	New	120.00	60.00
8	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	60.00	60.00
Gross Labour Cost (\$)			2,530.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >