

ESTIMATE OF REPAIR

Veh# : XD8243H

Accident Date : 19/10/2024

Location : SUNGEI KADUT CRESCENT

Model:

ISUZU FX277M

(16/12/2013 - 15/12/2028)

3P:

YP509U (SOMPO)

TP Somp
Hui Rong

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front side mirror RH <i>Damaged</i>	237.60	✓	
2	1 pc	Front side mirror arm RH <i>Bent</i>	367.50	✓	
3	1 pc	Front round mirror RH <i>Not new</i>	105.10	X	
4	1 pc	Front door RH <i>Repair</i>	1,605.60	X	
5	1 pc	Front door protector garnish RH <i>Cracked</i>	348.60	✓	
6	1 pc	Front door protector garnish lamp RH <i>Cracked</i>	86.40	✓	
7	1 pc	Front door protector garnish lamp cover RH <i>Cracked</i>	55.60	✓	
8	1 set	Front door protector garnish clip RH <i>New</i>		40.00	✓
9	1 set	Front door inner trim board clip RH <i>Not new</i>		50.00	X
10	1 pc	Front corner garnish RH <i>Cracked</i>	339.60	✓	
11	1 pc	Front corner lower garnish RH <i>Not new</i>	95.10	X	
12	1 set	Front corner garnish clip RH <i>New</i>		40.00	✓
13	1 pc	Front grille <i>Cracked</i>	569.00	✓	
14	1 set	Front grille clip <i>New</i>		40.00	✓
15	1 pc	Front headlamp RH <i>Smashed</i>	505.00	✓	
16	1 pc	Front headlamp bracket RH <i>Distorted</i>	364.00	✓	
17	1 pc	Front headlamp side bracket RH	87.00	✓	
18	1 pc	Front side lamp RH <i>Smashed</i>	330.20	✓	
19	1 pc	Front bumper <i>Distorted</i>	1085.00	✓	
20	2 pcs	Front bumper bracket R/L <i>RH Distorted</i>	430.00	2/5	
21	2 pcs	Front bumper top rubber pad R/L <i>Not new</i>	84.00	X	
22	1 pc	Front bumper garnish moulding RH <i>Damaged</i>	87.00	✓	
23	1 pc	Front Arch garnish RH <i>Torn</i>	535.00	✓	
24	1 pc	Front mudflap RH <i>Torn</i>	52.00	✓	
25	1 pc	Front upper step bracket RH	312.00	✓	
26	1 pc	Front upper step garnish RH	225.00	✓	
27	1 pc	Front upper step garnish reflector RH <i>Distorted</i>	59.00	✓	
28	1 set	Front lower step bracket RH	312.00	✓	
29	2 pcs	Front lower step garnish RH	218.00	✓	
30	1 pc	Front lower step bar bracket RH	459.00	✓	

31	1 pc	Front lower step bar bracket reflector RH	<i>Distorted</i>	62.00	✓	
32	1 pc	Front lower step garnish side cover RH		58.00	✓	
				Sub-Total:	9,074.30	170.00 0.00
					15%	0% 0%
				After Less %:	7,713.16	170.00 0.00
		Labour				
1		To remove & refix accident damaged parts & realign affected area.		1,000.00	600	
2		To spray paint on accident affected area.		1,000.00	800	
3		To remove & refix door mechanism.		100.00	X	
4		To check wiring & headlamp focus.		60.00	30	
5		To rust proof affected area.		60.00	40.	
				Sub-Total:	2,220.00	
				Total:	10,103.16	

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

*Adm Lj
w/s 06 Days.*



AL 8778 1999
24 hr accident call



total: 7514.07

1/s: 61c ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: