

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060236/APA3Q2**Date:** 14/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230084115
Claimant Vehicle No : SMH5262G **Insured Vehicle No :** SNM1908R
 Date of Loss: 23/06/2024 Nature of Claim: TP Claim No: 3736111173SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH5262G**
 Make & Model: MAZDA 6, 2.0 SEDAN STANDARD 2WD (A) Engine No: PE21254013
 Reg. Date: 25/01/2019 (Man. Year: 2018) Chassis No: JM6GL1072K0311619
 Colour: White Odometer: 43703 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,962.48	10,647.44	10,315.04	49.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,160.00	2,530.00	53.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,652.48	12,807.44	12,845.04	50.07
Approved Total (Overridden) (S\$)		10,100.00		
Nett Amount (S\$)	25,652.48	10,100.00	15,552.48	60.63
+ Loss of Use (8.0 x S\$90.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		10,847.25		

INSPECTION

Date of Assignment: 26/06/2024
 Date Inspected: 26/06/2024 Inspected At: Sin Yu Sin Workshop (HQ)
 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	58.90 FL	*- FL
2	1		*FRONT BUMPER	Torn	1,211.90 FL	*1,211.90 FL
3	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	97.80 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	585.90 FL	*585.90 FL
5	1		*FRONT BUMPER REINFORCEMENT COVER	Torn	190.40 FL	*190.40 FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	47.20 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Cracked	103.40 FL	*103.40 FL
8	1		*FRONT BUMPER BRACKET	N/S Cracked	121.60 FL	*60.80 FL
9	4		*FRONT BUMPER SENSOR	Not Necessary	821.60 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Cracked	138.50 FL	*138.50 FL
11	1		*FRONT BUMPER TOP GARNISH	Repair	320.50 FL	*- FL
12	1		*FRONT BUMPER UNDERCOVER	Not Necessary	235.90 FL	*- FL
13	1		*FRONT GRILLE	Cracked	673.80 FL	*673.80 FL
14	1		*FRONT GRILLE LOGO	Necessary	107.90 FL	*107.90 FL
15	2		*FRONT GRILLE CHROME MOULDING	Cracked	352.60 FL	*352.60 FL
16	1		*HEADLAMP	N/S Cracked	9,158.20 FL	*3,369.00 FL
17	1		*FRONT BRACE PANEL	Not Necessary	75.20 FL	*- FL
18	1		*RADIATOR PANEL SUPPORT FRAME	Cracked	746.50 FL	*746.50 FL
19	1		*REAR BUMPER	Deformed	1,099.40 FL	*1,099.40 FL
20	2		*REAR BUMPER SIDE HOLDER	Not Necessary	85.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR	Not Necessary	107.80 FL	*- FL
22	2		*REAR BUMPER TOW COVER	Not Necessary	93.20 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Dented	583.30 FL	*583.30 FL
24	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	842.40 FL	*411.20 FL
25	4		*REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
26	1		*REAR END PANEL	Repair	542.20 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	180.10 FL	*180.10 FL
28	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	179.80 FL	*- FL
29	1		*TAILLAMP	N/S Cracked	3,184.60 FL	*1,592.30 FL
30	1		*BOOTLID	Dented	1,245.50 FL	*1,245.50 FL
31	1		*BOOTLID LOCK	Damaged	184.90 FL	*184.90 FL
32	1		*BOOTLID WEATHERSTRIPE	Not Necessary	287.40 FL	*- FL
33	2		*BOOTLID REFLECTOR	Not Necessary	1,517.80 FL	*- FL
34	1		*MAZDA LOGO	Necessary	58.90 FL	*58.90 FL
35	1		*MAZDA 6 WORDING	Necessary	65.10 FL	*65.10 FL
36	1		*SKYACTIV EMBLEM	Necessary	60.40 FL	*60.40 FL
37	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
38	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
39	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
42	1		*RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS
43	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
44	1		*REAR BUMPER STICKER WRAP	Not Necessary	280.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
46	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,055.60	13,271.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,093.12	2,624.36
Total Parts (\$\$)	20,962.48	10,647.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	900.00
2	SPRAY PAINTING	New	1,600.00	800.00
3	WIRING	New	100.00	60.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	New	120.00	60.00
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	New	120.00	60.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE UPHOLSTERY	New	150.00	30.00
11	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			4,690.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >