

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100473/UPA3Q2
Date: 13/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : FBR1090P Insured Vehicle No : GBL1373E
Date of Loss: 19/10/2024 Nature of Claim: TP Claim No: MFL2024D0013816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBR1090P
Make & Model: TRIUMPH BONNEVILLE T120 DIAMOND, 1.2 Engine No: H965068
Reg. Date: 25/02/2020 (Man. Year: 2019) Chassis No: SMTDAD75HWL962960
Colour: White Odometer: 25465 km
Engine Capacity: 1198 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80Z R18 Rear Tyre Size: 150/70Z R17
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,329.00	11,399.40	4,929.60	30.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	500.00	350.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,179.00	11,899.40	5,279.60	30.73
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	17,179.00	9,500.00	7,679.00	44.70
+ GST 9.00/9.00% (S\$)	1,546.11	855.00	691.11	44.70
Nett Amount (S\$)	18,725.11	10,355.00	8,370.11	44.70
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		10,457.18		

INSPECTION

Date of Assignment: 28/10/2024
Date Inspected: 28/10/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
Industrial City
Singapore 533758
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Feb 2025)	
Parts:	N/A	TRIUMPH BONNEVILLE T120 DIAMOND 1.2 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR1090P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE	Cut	80.00 F	*80.00 FL
2	1		*BAR HANDLE	Bent	498.00 F	*498.00 FL
3	1		*BEARING SAC (55 X 30 X17)	Not Necessary	81.00 F	*- FL
4	1		*BEARING STEERING CONE LOWER /UPPER	Not Necessary	88.00 F	*- FL
5	2		*BOLT (M10X65)	Necessary	22.00 F	*22.00 FL
6	1		*BOLT FOOTREST	Cut	58.00 F	*58.00 FL
7	1		*BRACKET FRONT MUDGUARD	Bent	122.00 F	*122.00 FL
8	1		*BRACKET HEADLIGHT LH	Twisted	186.00 F	*186.00 FL
9	1		*BRACKET UNDER FORK	Repair	1,222.00 F	*- FL
10	2		*BUSH FOKR	Not Necessary	94.00 F	*- FL
11	2		*BUSH MAIN STAND	Not Necessary	68.00 F	*- FL
12	1		*CLAMP HANDLEBAR LOWER LH	Twisted	105.00 F	*105.00 FL
13	1		*CLAMP HANDLEBAR LOWER RH	Twisted	105.00 F	*105.00 FL
14	1		*COVER HEADSTOCK BEARING	Necessary	27.00 F	*27.00 FL
15	1		*FORK FRONT ASSY LH	Bent / Twisted	2,574.00 F	*2,256.00 FL
16	1		*FORK FRONT ASSY RH	Bent / Twisted	2,574.00 F	*2,256.00 FL
17	1		*LAMP SIGNAL FRONT LH	Cut	260.00 F	*260.00 FL
18	1		*LEVER CLUTCH	Cut	203.00 F	*203.00 FL
19	1		*MAIN STAND	Bent	323.00 F	*323.00 FL
20	1		*MUDGUARD FRONT	Cracked	870.00 F	*870.00 FL
21	2		*REFLECTOR FORK	Not Necessary	38.00 F	*- FL
22	4		*RUBBER HANDLE BAR	Necessary	84.00 F	*84.00 FL
23	1		*SEAL DUST STEERING CONE LOWER	Not Necessary	40.00 F	*- FL
24	1		*SEAL DUST STEERING CONE UPPER	Not Necessary	21.00 F	*- FL
25	1		*SEAL OIL FUEL PUMP	Necessary	108.00 F	*108.00 FL
26	1		*STAND SIDE	Cut	326.00 F	*326.00 FL
27	1		*STAY CASTING POLISHED MUDGUARD CENTER	Bent	128.00 F	*128.00 FL
28	1		*STAY LH POLISHED MUDGUARD	Bent	97.00 F	*97.00 FL
29	1		*STAY RH POLISHED MUDGUARD	Bent	97.00 F	*97.00 FL
30	1		*STOPPER MAIN STAND	Necessary	17.00 F	*17.00 FL
31	1		*TAN FUEL ASSY	Dented	5,813.00 F	*4,438.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **16,329.00** **12,666.00**
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 1,266.60

Total Parts (\$\$) **16,329.00** **11,399.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	850.00	500.00
Gross Labour Cost (\$\$)			850.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >