

ASS. REC. BY:

REF:

C9/AG2 24060237/Ky13

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JNB 8887 Yr Regn: 08, 11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A1Make: Narda 2 C.C. 1498Colour: M. Grey AC: Insured / Std / NI / NASp. Reading: 159023 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MM 6D E 10 Y 10 0177440Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 17/5/24 D.O.I. 26/6/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ EM not ready21/10 L1 Rep & 24501. Contn (Red & 3370.48, 58%)

Date/Time, File Pass to?

1) 20/10/2024 ☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LB.I: (\$

TP

7450

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

JNB 8887

Rear tailgate	R	\$ 972.00	✓
" " lock	R	\$ 321.00	X
" " w/screen midg	Mr	\$ 112.00	✓
" " emblem	Mr	\$ 43.00	✓
" " Mazda 2	Mr	\$ 29.00	✓
" " weather strip	Mr	\$ 218.00	X
Rear bumper	Bu	\$ 696.80	✓
" " retainer x2 @57.60	Sn	\$ 115.20	X
" " reverse sensor	depthen	\$ 300.00	Sn 200Sn
" no plate lamp x2 @126.20	also	\$ 252.40	Lt
Rear taillamp LH	Ln	\$ 394.70	X
" end panel	R	\$ 529.60	X
" " garnish	Ln	\$ 127.40	X

208

To repair and replace affected parts	\$ 900.00	50% ✓
To spray paint on affected parts	\$ 1000.00	55% ✓
To remove and refix rear w/screen	\$ 180.00	12% ✓
To replace rear reverse sensor	\$ 100.00	5% ✓
To check wiring	\$ 40.00	2% ✓
To remove and refix rear garnishes	\$ 100.00	5% ✓
Toll cost	\$ 100.00	3% ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized 4 days
1/15/24 \$ 2450/-
Permy After Paint