

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS		INSURANCE (S) PL	Ref:	CS/AGI24060237/Kqh3e2	
	(BUDGET DIRECT 190 CLEMENCEAU	INSURANCE)	Date:	24/10/2024	
		PPING CENTRE SINGAPORE 239924	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 4225S	Veh. Inspected	JNB 8887	
	Policy No.	P10408125R02	Coverage	0	
	Claim No.	C10029457/CH	Excess	\$0.00	
	Assign From	MICHAEL	Assign Date	25/06/2024	
2.	2. Vehicle Details				
	Make & Model	MAZDA 2 (A)	C.C	1498	
	Engine No.	ZYA13308	Year of Reg.	01/08/2011	
	Chassis No.	MM6DE10Y1C0177440	Colour	METALLIC GREY	
	Odometer	159023 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/55R15	TOYO	6	
	L/H Front Tyre	195/55R15	TOYO	6	
	R/H Rear Tyre	195/55R15	TOYO	7	
	L/H Rear Tyre	195/55R15	TOYO	7	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	17/05/2024	Inspection Date	26/06/2024	
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE			
		#05-14 SINGAPORE 575721			
5a.	a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
.,					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days