

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100480/EVP3E2**Date:** 14/11/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMN3708U **Insured Vehicle No :** SLK8062T

Date of Loss: 24/10/2024 Nature of Claim: TP Claim No: DMPC2401441H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN3708U**

Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH723727

Reg. Date: 02/08/2019 (Man. Year: 2018) Chassis No: KNAF1416MK5032394

Colour: Grey Odometer: 57862 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Roadstone 5 mm Rear Left Side: Roadstone 5 mm

Front Right Side: Roadstone 5 mm Rear Right Side: Roadstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,368.28	3,037.68	3,330.60	52.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,530.00	630.00	29.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,528.28	4,567.68	3,960.60	46.44
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	8,528.28	3,650.00	4,878.28	57.20
+ GST 9.00/9.00% (S\$)	767.55	328.50	439.05	57.20
Nett Amount (S\$)	9,295.83	3,978.50	5,317.33	57.20

INSPECTION

Date of Assignment: 28/10/2024

Date Inspected: 28/10/2024 Inspected At: My Car Consultant Pte Ltd (HQ)
60 Jalan Lam Huat,, Carros Centre #05-67/68
Singapore 737869

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2024)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN3708U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	985.20 FL	*985.20 FL
2	1		*BOOT LID LOCK	Not Necessary	174.00 FL	*- FL
3	1		*BOOT LID DETECTOR	Not Necessary	312.00 FL	*- FL
4	1		*BOOT LID EMBLEM CERATO	Necessary	52.00 FL	*52.00 FL
5	1		*BOOT LID EMBLEM CYCLE	Necessary	35.00 FL	*35.00 FL
6	1		*REAR BUMPER	Broken	851.00 FL	*698.00 FL
7	1		*REAR BUMPER LOWER LIP	Broken	712.00 FL	*264.00 FL
8	1		*REAR BUMPER SIDE RETAINER RH	Broken	16.00 FL	*16.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Broken	448.00 FL	*318.00 FL
10	1		*REAR BUMPER SPONGE	Not Necessary	188.00 FL	*- FL
11	1		*REAR BUMPER REFLECTOR COVER RH	Cut	318.00 FL	*159.00 FL
12	1		*REAR BUMPER REFLECTOR RH	Not Necessary	424.00 FL	*- FL
13	1		*REAR REVERSE SENSOR (4PCS)	Shorted (2Pcs Only)	1,416.00 FL	*200.00 FL
14	1		*REAR END PANEL	Dented	845.00 FL	*455.00 FL
15	1		*REAR END PANEL TOP GARNISH	Broken	143.00 FL	*143.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
18	1		*REAR END PANEL TOP GARNISH CLIP (4PCS)	Necessary	26.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,060.20	3,370.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	691.92	332.52
Total Parts (\$\$)	6,368.28	3,037.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	New	800.00	800.00
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	New	800.00	600.00
3	TUFF COAT	New	100.00	20.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	30.00
6	TRANSFER BOOTLID MECHANISM	New	80.00	50.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			2,160.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >