

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406

Singapore 539195

H/P : 9299 6636 Fax : 6285 7054

*n. + Arthur
near*

29/10/24

2/5 #5000

the she. the. the.

Date : 28-Oct-24

Estimated repair cost of SKZ 9926 C Hyundai Accent

<u>Qty</u>	<u>Description</u>		<u>Amt S(\$)</u>	
	<u>List Items</u>			
1	Rear boot lid <i>ru</i>		\$ 1,549.80	<i>q</i>
1	Rear boot lock <i>su</i>		\$ 250.80	<i>q</i>
1	Rear boot rubber <i>7m</i>	<i>182.80</i>	\$ 289.90	<i>2</i>
1	Rear boot "HYUNDAI" emblem <i>su</i>		\$ 88.00	<i>x</i>
1	Rear boot "ACCENT" emblem <i>su</i>		\$ 90.90	<i>x</i>
1	Rear taillamp -LH <i>cr</i>	<i>391.20</i>	\$ 400.50	
1	Rear end panel <i>Body</i>		\$ 557.50	
1	Rear end panel inner garnish <i>7m</i>	<i>242.50</i>	\$ 299.30	
1	Rear bumper <i>DD</i>	<i>484.30</i>	\$ 688.74	
1	Rear bumper top bracket <i>7m</i>		\$ 65.80	
1	Rear bumper reflector <i>1/5 cr</i>	<i>75.50</i>	\$ 99.80	
1	Rear bumper reinforcement <i>cr</i>	<i>391.20</i>	\$ 455.80	
2	Rear bumper side retainers <i>11</i>		\$ 181.94	<i>x</i>
1	Rear floor panel <i>crumpled/suc</i>		\$ 1,200.41	<i>✓</i>
2	Front headlamps <i>su</i>		\$ 2,500.00	<i>x</i>
2	Front headlamp lower brackets <i>11</i>		\$ 255.20	<i>x</i>
1	Front grille assy <i>1a</i>		\$ 385.00	<i>x</i>
1	Front grille logo <i>11</i>		\$ 52.00	<i>x</i>
1	Front bumper <i>De / Torn</i>	<i>601.20</i>	\$ 688.80	
2	Front bumper fog lamps <i>11</i>		\$ 391.60	<i>q</i>
1	Front bumper inner sponge <i>11</i>		\$ 133.80	<i>q</i>
1	Front bumper licence plate garnish <i>Torn</i>		\$ 97.60	<i>✓</i>
1	Front bumper reinforcement <i>ru</i>		\$ 695.80	<i>q</i>
2	Front bumper side retainers <i>11</i>		\$ 121.60	<i>x</i>
1	Front bumper tow hook cover <i>11</i>		\$ 45.00	<i>x</i>
			\$ 11,585.59	
		Less 10% <i>202</i>	\$ 1,158.56	
			\$ 10,427.03	

Special Nett Items

1	Rear bumper clip (1 set)	nee	\$	50.00	30
1	Rear number plate with holder	see	\$	50.00	X
1	Front bumper clip (1 set)	nee	\$	80.00	30
1	Front number plate with holder	see	\$	50.00	40
				\$	230.00

S/NLABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	
3	To remove and refit inner garnishes.		\$	180.00	60
4	To remove and refit rear reverse sensor.		\$	120.00	30
5	To transfer boot lid mechanism and wiring assembly.		\$	80.00	X
6	To apply undercoating.		\$	150.00	60
7	Panel beating.		\$	1,800.00	1200
8	To re-spray painting on the affected areas.		\$	1,700.00	1400
				\$	4,190.00

Grand Total :**\$ 14,847.03**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 4291-01
202
7-3432.81
5.4-100
L-2780
6312.81
202
5000