

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNH 6792A

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER	DEFORMED	\$1,699.00	\$1,150.00	
1	REAR BUMPER REFLECTOR LH	CRACKED	\$98.00	\$98.00	
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	\$45.00	\$0.00	
2	REAR BUMPER SIDE RETAINER (FRONT) @\$95.00	NOT NECESSARY	\$190.00	\$0.00	
2	REAR BUMPER SIDE RETAINER (REAR) @\$95.00	NOT NECESSARY	\$190.00	\$0.00	
1	REAR BUMPER SIDE INNER GARNISH LH	DEFORMED	\$158.00	\$158.00	
2	REAR BUMPER SENSOR LH @\$398.00	DAMAGED	\$796.00	\$398.00	
4	REAR BUMPER SENSOR HOLDER LH @\$45.00	NECESSARY	\$180.00	\$45.00	
1	REAR BUMPER BRACKET LH	NOT NECESSARY	\$58.00	\$0.00	
1	TAILLAMP LH	NOT NECESSARY	\$825.60	\$0.00	
1	REAR CORNER PANEL LH	DEFORMED	\$368.10	\$368.10	
1	REAR CORNER PANEL RETAINER LH	NOT NECESSARY	\$142.10	\$0.00	
1	REAR FENDER COWLING LH	NOT NECESSARY	\$172.00	\$0.00	
1	REAR AIR VENT LH	NOT NECESSARY	\$115.00	\$0.00	
1	REAR AIR VENT SIDE COVER LH	NOT NECESSARY	\$35.00	\$0.00	
	LESS 25.00% DISCOUNT		(\$1,267.95)	(\$554.28)	
		\$3,803.85	\$1,662.82		

	Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00				
1	REAR BUMPER LOWER LID (SPECIAL TYPE) (SN)	DEFORMED	\$1,800.00	\$1,000.00				
1	SET REAR BUMPER SIDE UPPER GARNISH RH CLIP (SN)	NOT NECESSARY	\$30.00	\$0.00				
1	SET REAR BUMPER SIDE INNER GARNISH CLIP (SN)	NECESSARY	\$30.00	\$20.00				
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00				
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00				
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00				
		\$2,040.00	\$1,050.00					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,600.00	\$300.00		
TO SPRAY PAINT AFFECTED AREA		\$1,200.00	\$500.00		
TUFF COAT	NOT NECESSARY	\$250.00	\$0.00		
REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	NOT NECESSARY	\$350.00	\$0.00		
CONDUCT WATER LEAKAGE TEST	NOT NECESSARY	\$100.00	\$0.00		
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$80.00	\$50.00		
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$180.00	\$0.00		
		\$3,760.00	\$850.00		
GRAND TOTAL		\$9,603.85	\$3,562.82		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,800.00		
Report Ref No: CS/FCI24100490/Anp3e2					

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.