



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100490/Anp3e2
16 RAFFLES QUAY	Date:	24/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 37J	Veh. Inspected	SNH 6792A
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24009386MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	28/10/2024

2. Vehicle Details

Make & Model	TOYOTA VELLFIRE	C.C	3456
Engine No.	2GRK714332	Year of Reg.	20/03/2019
Chassis No.	GGH300032119	Colour	BLACK
Odometer	176375 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50 R19	MICHELIN	6
L/H Front Tyre	235/50 R19	MICHELIN	6
R/H Rear Tyre	235/50 R19	MICHELIN	6
L/H Rear Tyre	235/50 R19	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2024	Inspection Date	28/10/2024
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days