

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III24100493/KVP3E2**Date:** 20/11/2024REFERENCE

Insured/Claimant:	CHOW CHENG HUA	Policy No:	D21MPC0007390	
Date of Loss:	25/10/2024	Nature of Claim:	OD	Claim No: MPC2024D0012781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ380Z		
Make & Model:	MINI COOPER S, 2.0 (A)	Engine No:	G398H688B48A20A
Reg. Date:	13/03/2018 (Man. Year: 2018)	Chassis No:	WMWLN720602G79636
Colour:	Metallic Red	Odometer:	159954 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,234.55	15,658.28	1,576.27	9.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,520.00	750.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,504.55	17,178.28	2,326.27	11.93
Approved Total (Overridden) (\$\$)		13,700.00		
- Excess (\$\$)	750.00	750.00	0.00	0.00
Nett Amount (\$\$)	18,754.55	12,950.00	5,804.55	30.95

INSPECTION

Date of Assignment:	29/10/2024	
Date Inspected:	29/10/2024	Inspected At: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2024)
Parts:	144	MINI COOPER S 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ380Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	791.35 FL	*791.35 FL
2	2		*FRONT BUMPER FOG LAMP	Serviceable	941.60 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	O/S Cracked	277.90 FL	*138.95 FL
4	2		*FRONT BUMPER TOP SIDE RUBBER SEAL	Necessary	70.40 FL	*70.40 FL
5	1		*FRONT BUMPER INNER FOAM	Cracked	156.85 FL	*156.85 FL
6	1		*FRONT BUMPER INNER REINFORCEMENT	Bent	596.80 FL	*596.80 FL
7	1		*FRONT BUMPER CENTRE TOP BLACK GARNISH	Cracked	148.60 FL	*148.60 FL
8	1		*FRONT BUMPER LOWER SKIRTING	Serviceable	285.30 FL	*- FL
9	2		*FRONT BUMPER LOWER SKIRTING SIDE COVER	Serviceable	118.00 FL	*- FL
10	1		*FRONT GRILLE	Cracked	280.80 FL	*280.80 FL
11	1		*FRONT GRILLE S EMBLEM	Necessary	65.50 FL	*65.50 FL
12	2		*HEADLAMP	Cracked	4,381.30 FL	*4,381.30 FL
13	2		*HEADLAMP BLACK TRIM	Cracked	316.00 FL	*316.00 FL
14	1		*FRONT BONNET	Bent	1,846.10 FL	*1,846.10 FL
15	1		*FRONT BONNET TOP AIR SCOOP	Missing	346.70 FL	*346.70 FL
16	1		*FRONT BONNET TOP MINI LOGO	Dented	65.10 FL	*65.10 FL
17	1		*FRONT BONNET LOCK	Jammed	107.65 FL	*107.65 FL
18	1		*FRONT BONNET HINGE	O/S Distorted	192.50 FN	*96.25 F
19	1		*FRONT BONNET INSULATOR	Deformed	201.10 FL	*201.10 FL
20	1		*SET FRONT BONNET INSULATOR CLIPS	Necessary	60.00 FL	*60.00 FL
21	1		*FRONT SUPPORT PANEL	Buckled	782.00 FL	*782.00 FL
22	1		*AIR CON CONDENSER	Punctured	1,068.80 FL	*1,068.80 FL
23	1		*RADIATOR	Punctured	941.60 FL	*941.60 FL
24	2		*FRONT WHEEL ARCH BLACK GARNISH	Mtg Cracked	308.20 FL	*308.20 FL
25	2		*SET FRONT WHEEL ARCH BLACK GARNISH CLIPS	Necessary	80.00 FL	*80.00 FL
26	1		*FRONT WIPER GARNISH TOP	Dented	193.00 FL	*193.00 FL
27	1		*FRONT WIPER GARNISH LOWER	Deformed	193.00 FL	*193.00 FL
28	1		*FRONT NUMBER PLATE	Serviceable	80.00 FS	*- FS
29	1		*BTL RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS
30	1		*EXHAUST MANIFOLD	Cracked	825.00 FL	*825.00 FL
31	2		*HEADLAMP BRACKET	Bent	440.00 FL	*440.00 FL
32	1		*V STRUT PANEL	Bent	183.00 FL	*183.00 FL
33	1		*AIR DUCT	Cracked	380.00 FL	*380.00 FL
34	1		*SET FRONT BONNET MOULDING	Dented	236.65 FL	*236.65 FL
35	2		*FRONT BONNET LOCK BRACKET	Distorted	244.00 FL	*244.00 FL
36	1		*FRONT BUMPER INNER REINFORCEMENT COVER	Mtg Cracked	320.00 FL	*320.00 FL
37	2		*FRONT BUMPER INNER PART LH & RH	Bent	560.00 FL	*560.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	18,134.80	16,474.70
- List Item Discount on L Items 5.00/5.00% (S\$)	890.62	816.42
- Nett Item Discount on N Items 5.00/0.00% (S\$)	9.63	0.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					17,234.55	15,658.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	1,000.00	800.00
3	TO REMOVE, REFIT A/C CONDENSER, RADIATOR AND ETC..., AND REFILL AIR CON GAS	New	150.00	100.00
4	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	0.00
Gross Labour Cost (S\$)			2,270.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >