

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060239/UVH3E2
Date: 25/07/2024REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG24000250
Claimant Vehicle No :	SKU2520L	Insured Vehicle No :	SJV742H
Date of Loss:	13/06/2024	Nature of Claim:	TP
		Claim No:	CDMPG24001495

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2520L	Engine No:	G4LLPS226765
Make & Model:	HYUNDAI KONA, 1.6 (A)	Chassis No:	KMHHE811VRU024482
Reg. Date:	04/10/2023 (Man. Year: 2023)	Odometer:	13769 km
Colour:	Grey		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R18	Rear Tyre Size:	215/55 R18
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,383.60	5,063.40	9,320.20	64.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,700.00	1,260.00	42.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,343.60	6,763.40	10,580.20	61.00
Approved Total (Overridden) (\$\$)		5,400.00		
Nett Amount (\$\$)	17,343.60	5,400.00	11,943.60	68.86

INSPECTION

Date of Assignment:	25/06/2024	MCS GARAGE (HQ)
Date Inspected:	25/06/2024 Inspected At:	10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE
Estimated Period of Repair:	5.0 days	Singapore 417868

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Jul 2024)	
Parts:	N/A	HYUNDAI KONA 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU2520L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	2,164.00 FL	*2,164.00 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	112.00 FL	*112.00 FL
3	1		*TAILGATE REFLECTOR	Not Necessary	1,305.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
5	1		*TAILGATE EMBLEM KONA	Necessary	89.00 FL	*89.00 FL
6	2		*TAILGATE LICENCE LAMPS	Not Necessary	130.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Serviceable	624.00 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Not Necessary	378.00 FL	*- FL
9	1		*TAILGATE W/STRIP	Serviceable	189.00 FL	*- FL
10	1		*REAR BUMPER	Distorted	1,015.00 FL	*1,015.00 FL
11	1		*REAR BUMPER LOWER GUARD	Distorted	642.00 FL	*642.00 FL
12	1		*REAR BUMPER LAMP - CTR	Cracked	225.00 FL	*225.00 FL
13	2		*REAR BUMPER SIDES - L/R	Deformed / Twisted	890.00 FL	*890.00 FL
14	2		*REAR BUMPER SIDE RETAINERS - L/R	Not Necessary	170.00 FL	*- FL
15	1		*REAR BUMPER PDC SENSORS (4PCS)	Malfunction (1Pc Only)	900.00 FL	*225.00 FL
16	2		*REAR BUMPER LAMPS - L/R	Not Necessary	2,248.00 FL	*- FL
17	1		*REAR END PANEL	Repair	729.00 FL	*- FL
18	1		*REAR END PANEL GARNISH	Serviceable	146.00 FL	*- FL
19	1		*REAR EXHAUST SILENCER	Repair	1,341.00 FL	*- FL
20	1		*REAR EXHAUST INSULATOR	Twisted	189.00 FL	*189.00 FL
21	3		*REAR EXHAUST MOUNTINGS	Not Necessary	66.00 FL	*- FL
22	2		*REAR CORNER RADAR UNIT ASSYS - L/R	Not Necessary	2,536.00 FL	*- FL
23	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	182.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT	Cracked	582.00 FL	*582.00 FL
25	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
27	1		*SET REAR NO. PLATE	Bent	60.00 FS	*35.00 FS
28	1		*REAR REVERSE CAMERA	Serviceable	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,767.00	6,303.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,383.40	1,239.60
Total Parts (\$\$)	14,383.60	5,063.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	120.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
4	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
5	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	100.00	0.00
6	TO RESPRAY UNDERCOATING	New	80.00	40.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
8	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,080.00	600.00
Gross Labour Cost (S\$)			2,960.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >