

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SND 8999D

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	FRONT BUMPER	DEFORMED/TORN	\$861.90	\$861.90		
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$180.63	\$0.00		
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$477.73	\$0.00		
2	FRONT BUMPER SIDE RETAINERS - L/R @\$86.55	N/S BENT	\$173.10	\$86.55		
1	FRONT FENDER - LH	TO REPAIR SEE LABOUR	\$731.66	\$0.00		
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	\$181.43	\$0.00		
1	FRONT GRILLE	NOT NECESSARY	\$481.93	\$0.00		
1	FRONT HEADLAMP - LH	CRACKED	\$1,260.90	\$1,260.90		
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	\$831.10	\$0.00		
1	AIR CLEANER INTAKE HOSE	NOT NECESSARY	\$191.60	\$0.00		
	LESS 25.00% DISCOUNT		(\$1,343.00)	(\$552.34)		
			\$4,028.98	\$1,657.01		
Owner to LN - M						

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$40.00		
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00		
			\$110.00	\$40.00		

Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
	TO RESPRAY UNDERCOATING	NOT NECESSARY	\$50.00	\$0.00	
	TO CHECK FRONT ELECTRICAL WIRING		\$50.00	\$20.00	
	TO RESPRAY PAINTING AND ETC		\$800.00	\$450.00	
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER - LH AND FRONT SUPPORT PANEL		\$800.00	\$600.00	
		\$1,700.00	\$1,070.00		

GRAND TOTAL	\$5,838.98	\$2,767.01		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,200.00		
Report Ref No: CS/INC24100497/Uvh3e2				



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

TOTAL FOR SPARE PARTS: \$ 4,138.98 \$ 1,697.01
TOTAL FOR LABOUR: \$ 1,700.00 \$ 1,070.00
TOTAL REPAIR COST: \$ 5,838.98 \$ 2,767.01

## **CKS**

MARCUS CHUA KANG SENG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.