



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhbhm.com.sg
Company Reg. No. 202341776E

Vehicle No.: SKR3029Z
Make/Model : Toyota Altis
Chassis no.: MR053ZEE106178118
Year of Manufacture : 2010

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: SLN5678T

Accident Date : 23 Oct 2024

Type of repair: Lump Sump

Estimate cost of repairs

Qty	Part Description	Unit Price	Total Price
1 pc	Rear bumper <i>Distorted</i>	\$ 524.00	\$ 524.00 ✓
1 pc	Rear bumper reflector <i>new</i>	\$ 75.20	\$ 75.20 x
1 pc	Rear bumper retainers RH <i>new</i>	\$ 133.00	\$ 133.00 x
1 pc	Rear bumper reinforcement bracket RH <i>Distorted</i>	\$ 105.90	\$ 105.90 ✓
1 pc	Rear bumper sponge <i>Cracked</i>	\$ 175.00	\$ 175.00 ✓
			\$ 1,013.10
Less 25%			\$ (253.28)
			\$ 759.83
1 set	Reverse sensor <i>new</i>	\$ 250.00	SN <i>200</i>
1 set	Rear bumper clips <i>new</i>	\$ 50.00	SN <i>30</i>
1 set	Rear end panel sealant <i>new</i>	\$ 60.00	SN x
			\$ 360.00
1 job	To putty, spray paint and polish affected areas	\$ 600.00	200
1 job	Wiring Charges	\$ 60.00	30 x
1 job	To tuff kote	\$ 60.00	x
1 job	To install new reverse sensor	\$ 120.00	50
1 job	Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.	\$ 800.00	200
			\$ 1,640.00
Grand-total			\$ 2,759.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand-total

total: 1283.67

H/S: IK ✓

1 of 1

Adrian Lj
2/5 29/10/24
03 Days