



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGK 9788K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET 'LOGO' EMBLEM	NECESSARY	\$125.00	\$125.00
1	FRONT BONNET (ALUMINIUM)	TO REPAIR SEE LABOUR	\$1,890.00	\$0.00
1	FRONT BONNET MECHANISM LOCK RH	NOT NECESSARY	\$145.00	\$0.00
1	FRONT BUMPER	DEFORMED	\$1,790.00	\$1,790.00
1	FRONT BUMPER INNER FRAME BRACKET	CRACKED	\$325.00	\$325.00
1	FRONT BUMPER LOWER GRILLE	CUT	\$223.00	\$223.00
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	\$115.00	\$0.00
2	FRONT BUMPER PARKING SENSOR @\$215.00	NOT NECESSARY	\$430.00	\$0.00
1	FRONT BUMPER RH FOGLAMP GARNISH	CUT	\$125.00	\$125.00
2	FRONT BUMPER SIDE RETAINER L/R @\$75.00	NOT NECESSARY	\$150.00	\$0.00
1	FRONT BUMPER SPONGE	CRACKED	\$145.00	\$145.00
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	\$70.00	\$0.00
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	\$98.00	\$98.00
1	FRONT GRILLE 'LOGO' EMBLEM BASE	NOT NECESSARY	\$105.00	\$0.00
1	FRONT GRILLE (BASE)	CRACKED	\$305.00	\$305.00
1	FRONT GRILLE OUTER COVER WITH CHROME MOULDING	CRACKED	\$415.00	\$415.00
1	FRONT RH HEADLAMP	CUT	\$3,725.00	\$3,725.00
	LESS 10.00% DISCOUNT		(\$1,018.10)	(\$727.60)
			\$9,162.90	\$6,548.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	FRONT BUMPER NUMER PLATE (SN)	DENTED	\$25.00	\$25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$155.00	\$55.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		\$80.00	\$80.00
	TO RESET SYSTEM AFTER REPAIR WORKS	NOT NECESSARY	\$400.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$800.00	\$500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET (ALUMINIUM)		\$700.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$100.00	\$0.00
			\$2,080.00	\$880.00
GRAND TOTAL			\$11,397.90	\$7,483.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$6,000.00
Report Ref No: CS/INC24100504/Avh3m4				

TOTAL FOR SPARE PARTS: \$ 9,317.90 \$ 6,603.40
TOTAL FOR LABOUR : \$ 2,080.00 \$ 880.00
TOTAL REPAIR COST: \$11,397.90 \$ 7,483.40

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.