



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGT 1298M

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDE MIRROR ASSY RH (N)	CRACKED	\$1,650.00	\$1,220.10
	LESS 10.00%		(\$165.00)	(\$122.01)
			\$1,485.00	\$1,098.09
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT }		\$350.00	\$150.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT }		\$350.00	\$0.00
	CHECK THE WIRING AND LIGHTING SYSTEM ON AFFECTED AND CONSISTENT AREAS		\$120.00	\$30.00
			\$820.00	\$180.00
<b>GRAND TOTAL</b>			<b>\$2,305.00</b>	<b>\$1,278.09</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>\$1,000.00</b>
Report Ref No: CS/AGI24060240/Uvh3				

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser