

JOHN AUTO SERVICES

(53315321B)

IVY Qig Jia Wen

WDD 212

SGV 7188Y

Date 10/10/24 NO.

1.	Rear bumper / RR	1633 /	\$ 1806.44	
2.	Rear RH bumper Moulding / CUT	105 /	160.30	
3.	Rear RH bumper Retainer x nn		91.98	
4.	Rear RH tail lamp Assy x nn		706.50	
5.	Rear RH Road wheel / CUT		858.38 /	
6.	Rear RH wheel Bearing x nn		485.30	
7.	Rear RH TYRE x nn		450.00 SW.	
8.	Rear bumper RH inner Support x nn		26.29	
9.	1 Set Rear bumper Clip / nn	30 /	50.00 SW.	
10.	Rear fender RH x R		3,870.17	
11.	Rear glass Sealant x nn		150.00	
	* Rear bumper moulding (center & LH) / nec			
	Labour Charge.			
1.	To Remove & Refit Rear Glass.		150.00	X
2.	Rear bumper Sensor To Remove & Refit		120.00	30 /
3.	wiring fee		50.00	30 /
4.	To Repair Rear RH under Carriage		150.00	X
5.	wheel alignment.		120.00	30 /
6.	Respray Painted Damaged area.		1,000.00	450
7.	To Repair Damaged Portion		1,500.00	350
8.	Rear Boot & Rear fender Trim Bead Remove & Refit		480.00	X

Steve (LKK)

11/11/24, 11.00 am

m n

L/S, My A.K., 4 days

JOHN AUTO SERVICES

(53315321B)

11, Mandai Estate, #01-08 Eldix,
Singapore 729908 HP: 85081258

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: