

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 4550R

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT HEADLAMP LH | CRACKED | 865.00 | 610.00 |
| 1 | FRONT HEADLAMP LOWER GARNISH | DEFORMED | 348.60 | 348.60 |
| 1 | FRONT GRILLE ASSY | NOT NECESSARY | 507.10 | - |
| 1 | FRONT GRILLE LOGO | NOT NECESSARY | 75.20 | - |
| 1 | FRONT BUMPER | DEFORMED | 640.90 | 640.90 |
| 1 | FRONT BUMPER FOG LAMP COVER | NOT NECESSARY | 91.60 | - |
| 1 | FRONT BUMPER INNER SPONGE | CRACKED | 280.70 | 108.00 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 591.90 | - |
| 1 | FRONT BUMPER SIDE RETAINER | NOT NECESSARY | 40.20 | - |
| 1 | FRONT FENDER LH | NOT NECESSARY | 548.80 | - |
| 1 | FRONT FENDER INNER SHIELD | NOT NECESSARY | 77.10 | - |
| | LESS 10% DISCOUNT | | -406.71 | -170.75 |
| | | | 3,660.39 | 1,536.75 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | 50.00 | 30.00 |
| 1 | SET FRONT FENDER INNER SHIELD CLIP (SN) | NOT NECESSARY | 35.00 | - |
| | | | 85.00 | 30.00 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING ,LIGHTING AND RESETTING HEADLAMPS FOCUSING. | | 80.00 | 30.00 |
| | TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL. | NOT NECESSARY | 100.00 | - |
| | TO PPROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIR INCLUDING CUT,AND WELD,REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. | | 1,400.00 | 200.00 |
| | TO RESPRAY PAINTING INCLUDE POLISHING WAXING ON THE CHARGED BODY PARTS ,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT. | | 1,300.00 | 100.00 |
| | | | 2,880.00 | 330.00 |
| | GRAND TOTAL | | 6,625.39 | 1,896.75 |
| | | | | |

Report Ref No. CS/FCI24100516/Avp3q2(N)



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,500.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/FCI24100516/Avp3q2(N)



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.