



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 1014U

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH/ HEADLAMP UNIT (SN)	CUT	\$3,989.21	\$3,989.21
			\$3,989.21	\$3,989.21
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPAIR RIGHT FRONT FENDER		\$240.00	\$240.00
	PAINT RIGHT FRONT FENDER, STAGE 3 MET/STD, BASE AND CLEAR SYSTEM		\$800.00	\$800.00
	REMOVE / INSTALL RIGHT FRONT LAMP UNIT		\$96.00	\$96.00
			\$1,136.00	\$1,136.00
GRAND TOTAL			\$5,125.21	\$5,125.21
RECOMMENDED COST OF REPAIRS				\$5,125.21
Report Ref No: CS/MSG24100518/Enp3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.