



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2501370
3 ANSON ROAD #16-00	INV Date	10/03/2025
SPRINGLEAF TOWER	Reference	CD/CTI24100525/Kma3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	PC 7901Z
Insured Veh.	PC 7152T
Claim No.	SNM24D206045
Policy No.	DMB1SNA00006472404
Accident Date	24/10/2024
Inspection Date	28/10/2025

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (9%)</b>	<b>36.00</b>
<b>Grand Total</b>	<b>436.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Ref: CD/CTI24100525/Kma3q2 Date: 10/03/2025 Code: CTI
--	---

### 1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	PC 7152T	Veh. Inspected	PC 7901Z
Policy No.	DMB1SNA00006472404	Coverage	0
Claim No.	SNM24D206045	Excess	\$0.00
Assign From	LYNN KHONG	Assign Date	29/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE COMMUTER 2.8 GL AT	C.C	2754
Engine No.	1GD8324652	Year of Reg.	16/05/2019
Chassis No.	GDH2232000860	Colour	SILVER
Odometer	402148 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15X8	BRIDGESTONE	9
L/H Front Tyre	195R15X8	BRIDGESTONE	9
R/H Rear Tyre	195R15X8	BRIDGESTONE	9
L/H Rear Tyre	195R15X8	BRIDGESTONE	9

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/10/2024	Inspection Date	28/10/2024
Survey held at	SERVE YOU MOTOR PTE LTD BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 7901Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DENTED / CUT	\$696.40	\$696.40
1	RH FRONT BUMPER RETAINER	CRACKED	\$270.20	\$125.00
1	FRONT RH HEAD LAMP	CUT	\$2,994.30	\$2,539.10
1	FRONT RH DOOR ASSY	BENT	\$1,828.00	\$1,721.10
1	FRONT BUMPER RH SIDE RETAINER	CRACKED	\$118.00	\$118.00
1	FRONT RH SIDE MIRROR ASSY	CRACKED	\$981.90	\$981.90
2	FRONT RH DOOR HINGES TOP/LOWER @\$225.00	TO REPAIR SEE LABOUR	\$450.00	\$0.00
1	FRONT RH STEP GARNISH	SERVICEABLE	\$352.80	\$0.00
1	FRONT CORNER PANEL RH	BENT	\$268.00	\$268.00
	<b>LESS 25.00% DISCOUNT</b>		(\$1,989.90)	(\$1,612.38)
			\$5,969.70	\$4,837.12

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$78.75	\$50.00
1	RH CCTV CAMERA (SN)	DENTED	\$480.00	\$280.00
			\$558.75	\$330.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE /RENEW /REFIT /KNOCKING/STRAIGHTEN THE ACCIDENT DAMAGED PORTION .TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR HINGES TOP/LOWER.		\$880.00	\$500.00
	LABOUR FOR DISMANTLE AND REFIT FRONT DOOR COMPARTMENT/ACCESSORIES		\$150.00	\$60.00
	LABOUR FOR DISMANTLE CCTV		\$180.00	\$40.00
	SUPPLY SPRAY PAINT ON ACCIDENT DAMAGE SIDE MATERIAL AND NECESSARY ITEMS		\$1,000.00	\$350.00
			\$2,210.00	\$950.00

<b>GRAND TOTAL</b>			<b>\$8,738.45</b>	<b>\$6,117.12</b>
--------------------	--	--	-------------------	-------------------

	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$4,850.00</b>
--	---	--	--	-------------------

Report Ref No: CD/CTI24100525/Kma3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

**PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z**




**PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z**




**PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z**



**PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z**



**PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 6 of 6)

### PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : PC 7901Z

