

*NOT Authorized*

Ins: China Taiping Insurance (Sinagpore) Pte Ltd  
 Company: RET Tours Pte Ltd  
 Registration no. : PC 7901 Z TOYOTA / HIACE COMMUTER GL 2.8 GL AT  
 Acc/date: 24/10/2024  
 Date : 28/10/2024  
 Quotation No. : 79011024

*11 Pmg @ 4850p  
 Accruing After Paim*

S/N	Qty	Particulars	Amount
-----	-----	-------------	--------

LIST ITEMS

1	1	Front Bumper	<i>nd/cvt</i> 696.4 ✓
2	1	RH Front Bumper Retainer <i>125</i>	<i>cm</i> 270.2
3	1	Front RH Head Lamp <i>2539.10</i>	<i>cm</i> ✓ 2994.3
4	1	Front RH door assy <i>1721.10</i>	<i>cm</i> ✓ 1828.0
5	1	Front bumper RH side retainer	<i>cm</i> ✓ 118.0
6	1 set	Front bumper clip	<i>cm</i> 505.0 105.0
7	1	Front RH Side Mirror Assy	<i>cm</i> ✓ 981.9
8	2	Front RH door hinges Top/Lower	225 each <i>R</i> X 450.0
9	1	Front RH step garnish	<i>R</i> X 352.8
10	1	Front corner panel RH	<i>cm</i> ✓ 268.0
			8064.6
Less: 25%			-2016.1
			<b>\$ 6,048.45</b>

SPECIAL NETT ITEMS

1	1	RH CCTV camera	<i>nd</i> <i>Wasn</i> 480.0
			<b>\$ 480.00</b>

LABOUR & MISC CHARGES

1		To dismantle / renew / refit / knocking / straighten the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	<i>\$ 500</i> 880.00
2		Labour for dismantle and refit Front door compartment / accessories.	<i>\$ 600</i> 150.00
3		Labour for dismantle CCTV .	<i>\$ 400</i> 180.00
4		Supply spray paint on accident damage side material and necessary items	<i>\$ 3500</i> 1,000.00
			<b>\$ 2,210.00</b>

**Total Parts and Labour Cost of Repair \$ 8,738.45**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: