

ASS. REC. BY:

REF:

012 / 24100525 / kmaz

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 861K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PC 79018 Yr Regn: 05, 1P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy Hiace GL c.c. 2734

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 402148 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GDH 223. 2000860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil LS/Rlm / STD A/Rlm or

Tyre Size: F: 195R15 XJ

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 24/10/2

D.O.I. 28/10/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Est not ready

6/11 / L1 Rpt & 48501 Cont

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

S - RS. \$

Fixes

Others

TOTAL

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

*Not Authorized*  
*11/10/24 @ 4850*  
*Assuming After Rain*

Ins: China Taiping Insurance (Singapore) Pte Ltd  
 Company: RET Tours Pte Ltd  
 Registration no.: PC 7901 Z TOYOTA / HIACE COMMUTER GL 2.8 GL AT  
 Acc/date: 24/10/2024  
 Date: 28/10/2024  
 Quotation No.: 79011024

S/N	Qty	Particulars	Amount
<u>LIST ITEMS</u>			
1	1	Front Bumper	nd/cu ✓ 696.4
2	1	RH Front Bumper Retainer <i>125</i>	cm ✓ 270.2
3	1	Front RH Head Lamp <i>2539.10</i>	wt ✓ 2994.3
4	1	Front RH door assy <i>1721.10</i>	BM ✓ 1828.0
5	1	Front bumper RH side retainer	cm ✓ 118.0
6	1 set	Front bumper clip	Ma: 501w 105.0
7	1	Front RH Side Mirror Assy	cm ✓ 981.9
8	2	Front RH door hinges Top/Lower	225 each R X 450.0
9	1	Front RH step garnish	R X 352.8
10	1	Front corner panel RH	BM ✓ 268.0
			8064.6
Less: 25%			-2016.1
			<b>\$ 6,048.45</b>

<u>SPECIAL NETT ITEMS</u>			
1	1	RH CCTV camera	nd <i>Wasn</i> 480.0
			<b>\$ 480.00</b>

<u>LABOUR &amp; MISC CHARGES</u>			
1		To dismantle / renew / refit / knocking / straighten the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ <i>500</i> 880.00
2		Labour for dismantle and refit Front door compartment / accessories.	\$ <i>60</i> 150.00
3		Labour for dismantle CCTV .	\$ <i>40</i> 180.00
4		Supply spray paint on accident damage side material and necessary items	\$ <i>350</i> 1,000.00
			<b>\$ 2,210.00</b>

**Total Parts and Labour Cost of Repair \$ 8,738.45**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Costs once subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: