

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24060242/RMA3Q2**Date:** 17/01/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002556_01
Claimant Vehicle No : SLG8469A **Insured Vehicle No :** SMN8832K
 Date of Loss: 25/06/2024 Nature of Claim: TP Claim No: MFL2024D0008109

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG8469A**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRR954019
 Reg. Date: 17/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU803535820
 Colour: Grey Odometer: 802564 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,515.80	9,254.10	11,261.70	54.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,688.00	5,396.00	3,292.00	37.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,203.80	14,650.10	14,553.70	49.83
+ GST 9.00/9.00% (S\$)	2,628.34	1,318.51	1,309.83	49.83
Nett Amount (S\$)	31,832.14	15,968.61	15,863.53	49.83
+ Car Rental (8.0 x S\$81.69/day) (S\$)		653.52		
		16,622.13		
Liabile Amount (50.00%) (S\$)		8,311.07		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,313.25		

INSPECTION

Date of Assignment: 26/06/2024
 Date Inspected: 26/06/2024 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
 2 Pandan Crescent
 Singapore 128462
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** Daphne Lee Mooi Nghiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2024)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8469A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER ,FR BUMPER	Torn	799.30 FS	*799.30 FS
3	1		*SEAL ,HOOD TO FR END	Necessary	71.50 FS	*71.50 FS
4	1		*SUPPORT ,FR BUMPER	Cracked	121.30 FS	*121.30 FS
5	10		*PIECE ,RR BUMPER	Necessary	58.00 FS	*58.00 FS
6	1		*COVER ,FR BUMPER	Missing	40.70 FS	*40.70 FS
7	1		*GRILLE SUB-ASSY	Not Necessary	484.10 FS	*- FS
8	1		*HOOD SUB-ASSY	Repair	1,380.00 FS	*- FS
9	1		*FENDER SUB-ASSY FR	Buckled	1,488.90 FS	*1,488.90 FS
10	1		*LINER FR FENDER RH	Scratched	314.80 FS	*314.80 FS
11	2		*CLIP PIN HOLD	Necessary	5.00 FS	*5.00 FS
12	10		*CLIP	Necessary	38.00 FS	*38.00 FS
13	1		*HINGE ASSY ,HOOD RH	Serviceable	81.80 FS	*- FS
14	1		*SUPPORT RADIATOR	Serviceable	109.40 FS	*- FS
15	1		*BRACKET ,FR SIDE	Cracked	81.10 FS	*81.10 FS
16	1		*EMBLEM ,SIDE PANEL	Necessary	75.70 FS	*75.70 FS
17	1		*UNIT HEADLAMP	Cracked	4,063.00 FS	*4,063.00 FS
18	1		*COMPUTER SUB-ASSY	Serviceable	1,334.80 FS	*- FS
19	1		*LAMP ASSY ,FOG RH	Cracked	1,449.90 FS	*1,449.90 FS
20	1		*JAR ,WASHER A	Deformed	303.30 FS	*303.30 FS
21	1		*PIPE ,WASHER A	Serviceable	92.90 FS	*- FS
22	1		*PANEL SUB-ASSY FR	Repair	1,996.10 FS	*- FS
23	1		*WHEEL DISC	Serviceable	2,607.70 FS	*- FS
24	1		*CAP SUB-ASSY ,WHEEL	Cracked	293.60 FS	*293.60 FS
25	1		*ABSORBER SET ,SHOCK	Serviceable	616.00 FS	*- FS
26	1		*ARM SUB-ASSY	Not Necessary	1,166.90 FS	*- FS
27	1		*JOINT ASSY ,LWR BALL	Not Necessary	413.80 FS	*- FS
28	1		*HUB & BEARING ASSY	Not Necessary	928.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

20,515.80

9,254.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK LIGHTING & WIRING SYSTEM	New	198.00	198.00
2	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING	New	198.00	198.00
3	CONDUCT FULL WHEEL ALIGNMENT	New	198.00	198.00
4	REPLACE RH FRT SUSPENSION SYSTEM	New	792.00	0.00
5	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
6	REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	New	3,168.00	1,980.00
7	RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	New	3,936.00	2,624.00
Gross Labour Cost (\$\$)			8,688.00	5,396.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >