



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581	Ref: Date: Code:	CS/FCI24100532/Knp3m4 26/11/2024 FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8190X	Veh. Inspected	SGY 4673S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009549MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	30/10/2024
2. Vehicle Details			
Make & Model	TOYOTA COROLLA ALTIS 1.6 AUTO	C.C	1598
Engine No.	3ZZ4691850	Year of Reg.	27/09/2007
Chassis No.	MR053ZEC107154129	Colour	METALLIC SILVER
Odometer	164525 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	195/60R15	NEXEN	8
L/H Front Tyre	195/60R15	NEXEN	8
R/H Rear Tyre	195/60R15	NEXEN	9
L/H Rear Tyre	195/60R15	NEXEN	9
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/10/2024	Inspection Date	18/11/2024
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			