

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24100535/UNP3M4
Date: 21/11/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001195_05
Claimant Vehicle No :	SLR8881J	Insured Vehicle No :	GBB2063X
Date of Loss:	29/10/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8881J		
Make & Model:	MERCEDES-BENZ GLB 180, 1.3 PROGRESSIVE LINE (A)	Engine No:	28281480181264
Reg. Date:	01/08/2024 (Man. Year: 2024)	Chassis No:	W1N2476842W378794
Colour:	Black	Odometer:	3813 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,934.53	16,653.52	12,281.01	42.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,660.00	2,270.00	57.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,864.53	18,313.52	14,551.01	44.28
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	32,864.53	14,600.00	18,264.53	55.58

INSPECTION

Date of Assignment:	30/10/2024	
Date Inspected:	30/10/2024 Inspected At:	HONG AUTO SERVICES (KAKI BUKIT) 2 KAKI BUKIT AVENUE 2, #01-28 KAKI BUKIT AUTO HUB SINGAPORE 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLB 180 1.3 PROGRESSIVE LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8881J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	4,881.22 FL	*4,705.82 FL
2	1		*TAILGATE WINDSHIELD	Shattered	1,322.51 FL	*1,211.93 FL
3	2		*TAILGATE WINDSHIELD SIDE GARNISHES - L/R	Serviceable	423.00 FL	*- FL
4	1		*TAILGATE TOP SPOILER	Not Necessary	1,153.21 FL	*- FL
5	1		*TAILGATE WIPER ARM	Damaged	180.93 FL	*180.93 FL
6	1		*TAILGATE WIPER ARM COVER	Missing	55.63 FL	*55.63 FL
7	1		*TAILGATE WIPER MOTOR	Damaged/Jammed	591.66 FL	*591.66 FL
8	2		*TAILGATE LAMPS - L/R	Scratched/Cracked	1,102.46 FL	*854.28 FL
9	2		*TAILGATE LICENCE LAMPS	Not Necessary	179.90 FL	*- FL
10	1		*TAILGATE OPENING SWITCH	Damaged	280.63 FL	*280.63 FL
11	1		*TAILGATE INNER LOCK	Damaged	755.13 FL	*580.00 FL
12	1		*TAILGATE INNER TOP TRIM	Not Necessary	311.26 FL	*- FL
13	1		*TAILGATE INNER TRIM BOARD	Cut/Cracked	511.62 FL	*511.62 FL
14	1		*TAILGATE W/STRIP	Twisted	322.71 FL	*322.71 FL
15	2		*TAILGATE HINGES - L/R	Not Necessary	171.00 FL	*- FL
16	2		*TAILGATE DAMPERS - L/R	Not Necessary	1,782.20 FL	*- FL
17	2		*TAILGATE STOPPERS - L/R	Not Necessary	45.20 FL	*- FL
18	1		*TAILGATE M/B STAR	Necessary	89.95 FL	*89.95 FL
19	1		*TAILGATE M/B STAR CLIPS	Necessary	25.50 FL	*25.50 FL
20	1		*TAILGATE EMBLEM GLB 180	Necessary	141.20 FL	*141.20 FL
21	1		*TAILLAMPS - L/R	N/S Cracked/O/S Not Necessary	1,788.70 FL	*894.35 FL
22	2		*TAILLAMP LOWER BRACKETS - L/R	Not Necessary	173.20 FL	*- FL
23	1		*REAR BUMPER - TOP	Distorted	1,655.93 FL	*1,520.45 FL
24	1		*REAR BUMPER CHROME PLATE - TOP	Distorted	611.42 FL	*611.42 FL
25	1		*REAR BUMPER CTR PAD	Torn	811.33 FL	*811.33 FL
26	1		*REAR BUMPER BOTTOM CHROME TRIM	Cracked	1,471.43 FL	*1,471.43 FL
27	1		*REAR BUMPER BOTTOM COVER - CTR	Torn	681.62 FL	*681.62 FL
28	1		*REAR BUMPER REFLECTOR - LH	Serviceable	112.10 FL	*- FL
29	1		*REAR BUMPER PDC SENSORS - LH	Malfunction (2Pcs Only)	1,125.32 FL	*562.66 FL
30	1		*REAR BUMPER PDC SENSOR WIRE HARNESS	Serviceable	411.20 FL	*- FL
31	1		*REAR BUMPER REINFORCEMENT	Distorted	1,055.90 FL	*1,055.90 FL
32	1		*REAR BUMPER LOWER BRACKETS	N/S Twisted/O/S Not Necessary	220.40 FL	*110.20 FL
33	2		*REAR BUMPER SIDE RETAINERS - L/R	Not Necessary	231.20 FL	*- FL
34	1		*REAR END PANEL	Repair	1,015.60 FL	*- FL
35	1		*REAR END PANEL TRIM	Serviceable	280.93 FL	*- FL
36	1		*REAR EXHAUST CHROME TRIM - LH	Scratched/Bent	485.91 FL	*485.91 FL
37	1		*REAR EXHAUST INSULATOR	Not Necessary	281.60 FL	*- FL
38	1		*REAR EXHAUST SILENCER	Serviceable	1,895.60 FL	*- FL
39	2		*REAR FENDER ARC GARNISHES - L/R	Serviceable	799.24 FL	*- FL
40	1		*REAR FOOT ACTIVATED SENSOR	Cracked	391.23 FL	*391.23 FL
41	1		*REAR FENDER INNER TRIM - LH	Not Necessary	661.59 FL	*- FL
42	1		*SET REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
43	1		*REAR WINDSHIELD SOLAR FILM	Necessary	280.00 FS	*200.00 FS
44	1		*REAR RECORDER CAMERA	Serviceable	550.00 FS	*- FS
45	1		*REAR REVERSE CAMERA	Serviceable	420.00 FS	*- FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
47	1		*SET REAR NO. PLATE	Scratched	65.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	31,983.37 18,468.36
					- List Item Discount on L Items 10.00/10.00% (\$)	3,048.84 1,814.84
					Total Parts (\$)	28,934.53 16,653.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX TAILGATE WINDSHIELD	New	180.00	120.00
3	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	60.00
4	TO VACUUM, WAXING AND CLEANING INTERIOR	New	180.00	0.00
5	TO DIAGNOSE, ERASE FAULT MEMORY AFTER REPAIR	New	350.00	80.00
6	TO RESPRAY UNDERCOATING	New	120.00	30.00
7	TO RESPRAY PAINTING & ETC	New	1,400.00	800.00
8	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,500.00	550.00
Gross Labour Cost (\$\$)			3,930.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >