

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile	
MS	MS FIRST CAPITAL	. INSURANCE LTD	Ref:	CS/FCI24100543/Evh3e2	
	16 RAFFLES QUAY		Date:	20/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	SINGAI ONE 04030				
٠.	Insured Veh.	Policy Particulars :- T	Veh. Inspected	SKD 228J	
	Policy No.	D-24101860MFCT	Coverage	0	
	Claim No.	D24009510MFCT	Excess	\$0.00	
	Assign From	BETTY WONG	Assign Date	30/10/2024	
2.					
	Make & Model	MERCEDES BENZ E250	c.c	1796	
	Engine No.	27186030133911	Year of Reg.	02/11/2010	
	Chassis No.	WDD2073472F079603	Colour	BLUE/BLACK	
	Odometer	201631 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	275/30Z R20	PIRELLI	4	
	L/H Front Tyre	275/30Z R20	PIRELLI	4	
	R/H Rear Tyre	275/30Z R20	PIRELLI	4	
	L/H Rear Tyre	275/30Z R20	PIRELLI	4	
4.	L/H Rear Tyre	Description (4	
	L/H Rear Tyre			4	
THE	L/H Rear Tyre	Description of Description of DAMAGES AT THE N/S BODY.		4	
THE	L/H Rear Tyre VEHICLE SUSTAIN	Description of Description of DAMAGES AT THE N/S BODY.	of Damages	4	
THE	L/H Rear Tyre VEHICLE SUSTAIN	Description of Description of DAMAGES AT THE N/S BODY.	of Damages	01/11/2024	
THE	L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL	Description of ED DAMAGES AT THE N/S BODY. S. General In	of Damages formation Inspection Date	01/11/2024	
THE	L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date	Description of ED DAMAGES AT THE N/S BODY. S. General In: 24/10/2024	formation Inspection Date AVE 2 #01-14 AUT	01/11/2024	
THE DAM 5. 5a. A) DB) T	L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date Survey held at AMAGES CONSIST HE INSPECTION W/	Description of ED DAMAGES AT THE N/S BODY. S. General In: 24/10/2024 WJ AUTO SERVICES - 2 KAKI BUKIT	formation Inspection Date AVE 2 #01-14 AUT arks	01/11/2024 OHUB SINGAPORE 417921	

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days