

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110002/UPA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100401252
Claimant Vehicle No :	GBD9294P	Insured Vehicle No :	SKR3807U
Date of Loss:	29/10/2024	Nature of Claim:	TP
		Claim No:	5920683237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD9294P		
Make & Model:	KIA K2500, 2.5 D 6M/T (M)	Engine No:	D4CBE627475
Reg. Date:	14/07/2015 (Man. Year: 2014)	Chassis No:	KNCSJX76LF7930029
Colour:	Blue	Odometer:	272570 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6/6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,384.90	5,539.14	3,845.76	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	2,030.00	450.00	18.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,864.90	7,569.14	4,295.76	36.21
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	11,864.90	5,500.00	6,364.90	53.64
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.18		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		6,112.18		
Global Sum Settlement (S\$)		6,100.00		

INSPECTION

Date of Assignment:	01/11/2024	
Date Inspected:	01/11/2024 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	823.00 F	*823.00 FL
2	1		*FRONT PANEL GRILLE	Bent / Twisted	426.90 F	*299.00 FL
3	1		*FRONT KIA EMBLEM	Necessary	78.10 F	*78.10 FL
4	2		*FRONT HEAD LAMP	Cracked	704.30 F	*704.30 FL
5	1		*FRONT BUMPER	Distorted	359.00 F	*359.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	248.00 F	*- FL
7	1		*FRONT BUMPER GRILLE TOP	Twisted	328.50 F	*328.50 FL
8	1		*FRONT BUMPER GRILLE LOWER	Twisted	512.30 F	*286.00 FL
9	1		*FRONT NUMBER PLATE & BASE	Bent	48.00 FS	*40.00 FS
10	1		*REAR TAILGATE	Repair	1,698.00 F	*- FL
11	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
12	1		*REAR TAILGATE 13 PAX STICKER	Necessary	15.00 FS	*10.00 FS
13	1		*REAR KIA MOTORS WORDING STICKERS	Necessary	180.00 FS	*80.00 FS
14	1		*REAR TAILGATE LOWER PANEL RH	Badly Dented	1,455.10 F	*1,455.10 FL
15	1		*REAR TAIL LAMP RH	Cracked	272.20 F	*272.20 FL
16	1		*REAR TAIL LAMP HOUSING PANEL RH	Bent	190.60 F	*190.60 FL
17	1		*REAR EXHAUST PIPE	Bent / Twisted	809.10 F	*655.00 FL
18	1		*REAR SPARE TYRE CARRIER	Serviceable	670.00 F	*- FL
19	1		*REAR NUMBER PLATE LAMP	Cracked	65.00 F	*65.00 FL
20	1		*REAR NUMBER PLATE PANEL	Bent	126.20 F	*126.20 FL
21	1		*REAR NUMBER PLATE & BASE	Bent	48.00 FS	*40.00 FS
22	1		*REAR STEP PANEL	Bent / Cracked	312.60 F	*312.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,384.90	6,134.60
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	595.46
Total Parts (\$)	9,384.90	5,539.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS MECHANISM	New	80.00	0.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	0.00
4	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,100.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,480.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >