

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060244/UNH3E2
Date: 11/07/2024**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG24005974
Claimant Vehicle No :	SLK3512U	Insured Vehicle No :	SLZ3747E
Date of Loss:	23/06/2024	Nature of Claim:	TP
		Claim No:	CDMPG24001555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3512U	Engine No:	L15B4407413
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11207413
Reg. Date:	13/01/2017 (Man. Year: 2016)	Odometer:	82548 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50Z R18	Rear Tyre Size:	225/50Z R18
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,170.04	3,655.28	6,514.76	64.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,630.00	1,720.00	51.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,520.04	5,285.28	8,234.76	60.91
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	13,520.04	4,200.00	9,320.04	68.94

INSPECTION

Date of Assignment:	25/06/2024	GALAXY AUTO CARE PTE LTD (HQ) 13 KAKI BUKIT ROAD 4, #01-23 BARTLEY BIZ CENTRE Singapore 417807
Date Inspected:	26/06/2024 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3512U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,654.00 FL	*762.00 FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	98.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Cracked	325.00 FL	*151.00 FL
4	1		*REAR END PANEL	Dented	952.50 FL	*517.00 FL
5	1		*REAR END PANEL STRIKER	No such part	58.50 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Twisted	102.00 FL	*102.00 FL
7	1		*TAILGATE	Badly Dented	1,995.50 FL	*1,099.00 FL
8	1		*TAILGATE LOCK	Twisted / Damaged	495.50 FL	*280.00 FL
9	1		*TAILGATE LAMP RH	Not Necessary	552.00 FL	*- FL
10	2		*TAILGATE ABSORBER	Not Necessary	247.00 FL	*- FL
11	1		*TAILGATE LOGO	Not Necessary	108.00 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Serviceable	295.00 FL	*- FL
13	1		*TAILGATE INNER BOARD	Cracked	855.00 FL	*292.80 FL
14	1		*TAILGATE INNER PULL POCKET	Not Necessary	108.60 FL	*- FL
15	1		*TAILGATE CENTRE CHROME	Not Necessary	225.00 FL	*- FL
16	1		*TAILGATE TRIMBOARD TOP	Not Necessary	158.70 FL	*- FL
17	2		*TAILGATE HINGE	Not Necessary	199.00 FL	*- FL
18	1		*TAILLAMP RH	Cracked	480.60 FL	*480.60 FL
19	1		*REAR BUMPER SIDE RH	Buckled	280.40 FL	*280.40 FL
20	1		*TOOL SPONGE	Not Necessary	256.00 FL	*- FL
21	1		*REAR FENDER RH	Not Necessary	1,451.00 FL	*- FL
22	1		*REAR FENDER WHEEL ARCH RH	Torn	389.00 FL	*266.80 FL
23	1		*REAR FENDER INNER SHIELD RH	Not Necessary	325.00 FL	*- FL
24	1		*SET REAR NUMBER PLATE	Not Necessary	90.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET REVERSE SENSOR	Malfunction	480.00 FS	*200.00 FS
28	1		*REAR BUMPER REFLECTOR RH	Repeated	151.00 FS	*- FS
29	1		*SET TAILGATE REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,492.30	4,501.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,322.26	846.32
Total Parts (\$\$)	10,170.04	3,655.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	150.00	20.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
3	REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
4	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	New	150.00	60.00
5	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,300.00	600.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,300.00	750.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	50.00
Gross Labour Cost (\$)			3,350.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >