

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 9357G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO SUPPLY & INSTALL SCORPION TRUCK MOUNTED ATTENUATOR FOR TRUCK XD 9357G.		-	-
	MODULE A ENERGY ABSORBER.		40,000.00	30,000.00
	FULL LABOUR COST, DISMANTLING, REMOVING, INSTALLATION, REPAIRING AND ALIGNMENT.		6,000.00	2,500.00
			46,000.00	32,500.00
	GRAND TOTAL		46,000.00	32,500.00

RECOMMENDED COST OF LUMP SUM REPAIRS		26,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/LIP24110004/Kqh3e2(N)

KONG SENG CHEONG

**Licensed Appraiser**