

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|---|-----------------|--------------------------|--|
| | LIBERTY INSURA | NCE PTE LTD | Ref: | CS/LIP24110004/Kqh3e2(N) | |
| | ONE RAFFLES QU NORTH TOWER S | JAY #25-01 INGAPORE 048583 | Date: | 14/05/2025 | |
| | ATTN: ANDY SEAF | 1 | Code: | LIP | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | PC 7588U | Veh. Inspected | XD 9357G | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | IVS24/2036 | Excess (\$) | 0.00 | |
| | Assign From | ANDY SEAH | Assign Date | 30/10/2024 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | ISUZU FXZ77M | c.c | 9839 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | JALFXZ77ME7000094 | Colour | GOLD | |
| | Odometer | 485912 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 295/80 R22.5 | AGATE | 6 mm | |
| | L/H Front Tyre | 295/80 R22.5 | AGATE | 6 mm | |
| | R/H Rear Tyre | 295/80 R22.5 (D/D) | FULLRUN | 3/3/7/7 mm | |
| | L/H Rear Tyre | 295/80 R22.5 (D/D) | FULLRUN | 3/3/7/7 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 28/10/2024 | Inspection Date | 01/11/2024 | |
| | Survey held at | THIAM HENG HUAT PTE LTD | | | |
| | | 176 SIN MING DRIVE #05-14 SINGAPORE 575721 | | | |
| 5a. | Remarks | | | | |
| | A)REGISTRATION DATE: 13 AUG 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NOR | STIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days | | | |