

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110006/TQH3E2
Date: 11/04/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNG6166M	Insured Vehicle No :	SMH2022C
Date of Loss:	29/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401463H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG6166M	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 RWD, (A)	Chassis No:	LRW3F7FS3NC571854
Reg. Date:	02/06/2022 (Man. Year: 2022)	Odometer:	52116 km
Colour:	Red		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,655.22	1,176.99	478.23	28.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	3,260.00	1,460.00	30.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,375.22	4,436.99	1,938.23	30.40
+ GST 9.00/9.00% (S\$)	573.77	399.33	174.44	30.40
Nett Amount (S\$)	6,948.99	4,836.32	2,112.67	30.40

INSPECTION

Date of Assignment:	30/10/2024	
Date Inspected:	01/11/2024	Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609042
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2025)
Parts: 143	TESLA MODEL 3 RWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNG6166M)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	2		*SCREW GROMMET - S - 7X7H-0.65-1.5 GRP - PA6 - SEAL	Necessary	1.62 F	*1.62 F
3	1		*REAR T-BADGE	Necessary	40.74 F	*40.74 F
4	4		*LIFTGATE LAMP CONNECTOR GASKET	Necessary	52.96 F	*52.96 F
5	2		*BODYSIDE LAMP CONNECTOR GASKET	Necessary	26.48 F	*26.48 F
6	1		*ULTRASONIC SENSOR HPFL SHRINK UPA RADIAL - SUNSET RED	Distorted	178.27 F	*178.27 F
7	1		*M3 ASY RR BUMPER BEAM - EXTRUSION	Not Necessary	295.42 F	*- F
8	4		*SEMS, [FL], HX, M6X18, [88], G1009[B], MAT, ADH	Necessary	8.16 F	*8.16 F
9	4		*J - NUT M6 0.5 - 3.0 MULTITHREAD	Necessary	12.20 F	*12.20 F
10	1		*REAR FASCIA - LOWER - ASSEMBLY	Not Necessary	152.81 F	*- F
11	2		*U-NUT - M5 - 2MM GRIP - STEEL - ZNFL	Necessary	1.62 F	*1.62 F
12	1		*RR FASCIA UPTD WITH PARK ASSIST BRACKTS	Deformed	834.94 F	*834.94 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,655.22	1,176.99
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR BUMPER. ALL ACCIDENT AFFECTED AREA	New	1,440.00	1,080.00
2	TO RESPRAY REAR BUMPER & BOOTLID	New	2,400.00	1,600.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	180.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	250.00
			Gross Labour Cost (\$)	4,720.00
				3,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >