3/3/25, 11:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG24110007/EVH3M4

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 03/03/2025

REFERENCE

Insured/Claimant: JEET VIJAN Policy No: 2070052915

Date of Loss: 29/10/2024 Nature of Claim: OD Claim No: 5261403525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS9239R

Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC Engine No:

(17)(A)

Reg. Date: 20/03/2020 (Man. Year: 2020) Chassis No: WAUZZZF32L1076303

Colour: Black Odometer: 34925 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: S\$117,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65R17 Rear Tyre Size: 215/65R17
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		14,700.00	4,843.52	9,856.48	67.05
Miscellaneous Items		0.00	0.00	0.00	
Labour		19,432.00	4,152.00	15,280.00	78.63
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	34,132.00	8,995.52	25,136.48	73.64
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	33,332.00	8,195.52	25,136.48	75.41
	+ GST 9.00/9.00% (S\$)	2,999.88	737.60	2,262.28	75.41
	Nett Amount (S\$)	36,331.88	8,933.12	27,398.76	75.41

INSPECTION

Date of Assignment: 01/11/2024

Date Inspected: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

CZD890940

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	3,215.00 FS	*2,572.00 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	168.00 FS	*134.40 FS
3	1		*REAR DOOR CATCH - LH	Screw Loose	150.00 FS	*120.00 FS
4	1		*REAR DOOR HANDLE, EXTERIOR - LH	Cut	240.00 FS	*192.00 FS
5	1		*REAR DOOR HANDLE UNDERLAY - LH	Not Necessary	7.00 FS	*- FS
6	1		*REAR DOOR HANDLE HOUSING - LH	Not Necessary	34.00 FS	*- FS
7	1		*REAR DOOR MOUNTING BAR - LH	Not Necessary	186.00 FS	*-FS
8	1		*REAR DOOR LOWER COVER - LH	Cut	413.00 FS	*330.00 FS
9	1		*REAR FENDER - LH	Repair	4,503.00 FS	*-FS
10	1		*REAR QUARTER GLASS - LH	Not Necessary	769.00 FS	*-FS
11	1		*PRIMER	Not Necessary	27.00 FS	*-FS
12	1		*REAR WHEEL ARCH COVER - LH / RH	Cut	1,278.00 FS	*1,022.40 FS
13	1		*REAR BUMPER SPOILER	Cut	573.00 FS	*458.00 FS
14	1		*REAR CROSS REINFORCEMENT BRACKET - CENTER	Not Necessary	121.00 FS	*- FS
15	1		*REAR BUMPER BRACKET	Not Necessary	60.00 FS	*-FS
16	1		*REAR ALUMINIUM RIM LH	Not Necessary	1,576.00 FS	*- FS
17	1		*QUARTER GLASS SEALANT	Not Necessary	100.00 FS	*-FS
18	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*-FS
19	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*-FS
20	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
21	1		*CAVITY WAX	Not Necessary	140.00 FS	*-FS
22	1		*SUNDRIES	Necessary	500.00 FS	*14.72 FS
F=Fra	anchise	part. S=Spcl	Nett.	2		
				Total Parts (S\$)	14,700.00	4,843.52

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	l New	400.00	400.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC) New	1,800.00	0.00
5	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	1,250.00
6	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, REAR END PANELLING, ROOF CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, LHS REAR DOOR LOWER COVER, BOTH REAR WHEEL ARCH TRIM AND LHS REAR DOOR HANDLE	New	7,200.00	1,850.00
7	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST	New	500.00	0.00
8	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	0.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
	Gross Labour	r Cost (S\$)	19,432.00	4,152.00
	Report was unsubmitted during this p	orint-out		

< END OF ESTIMATES >