



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBS 5622Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER	CUT	\$320.00	\$220.00
1	FRONT FENDER SITE COVER - R/H	TO REPAIR SEE LABOUR	\$140.00	\$0.00
1	FRONT FORK ASSY	BENT/TWISTED	\$3,450.00	\$2,100.00
1	FRONT FORK UNDER BRACKET	SERVICEABLE	\$1,060.00	\$0.00
1	FRONT RIM	SERVICEABLE	\$1,250.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$165.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$98.00	\$0.00
1	HANDLE BAR	BENT	\$480.00	\$305.00
1	SET HANDLE BAR END	CUT	\$168.00	\$60.00
1	SET HAND GRIP	TORN	\$100.00	\$80.00
1	SET FRONT SIGNALS	CRACKED	\$325.00	\$160.00
1	SET FRONT MIRROR	MISSING	\$280.00	\$180.00
1	BRAKE LEVER	CUT	\$138.00	\$138.00
1	FUEL TANK COVER	DENTED	\$285.00	\$285.00
1	CENTRE COVER	NOT NECESSARY	\$155.00	\$0.00
1	FRONT FOOTREST - R/H	CUT	\$148.00	\$90.00
1	FRONT FOOTREST BRACKET -R/H	NOT NECESSARY	\$320.00	\$0.00
1	BRAKE PEDAL	CUT	\$180.00	\$150.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	\$1,800.00	\$0.00
1	EXHAUST PROTECTOR	CUT	\$220.00	\$220.00
1	EXHAUST PROTECTOR END CAP	CUT	\$145.00	\$90.00
1	REAR FOOTREST - R/H	NOT NECESSARY	\$138.00	\$0.00
1	REAR FOOTREST BRACKET - R/H	NOT NECESSARY	\$420.00	\$0.00
1	SET REAR SIGNAL	NOT NECESSARY	\$325.00	\$0.00
	LESS 10.00% DISCOUNT		(\$1,211.00)	(\$407.80)
			\$10,899.00	\$3,670.20

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	MISSING	\$38.00	\$20.00
2	FORK OIL (SN)	NOT NECESSARY	\$42.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK OIL SEAL (SN)	NOT NECESSARY	\$68.00	\$0.00
1	STEERING CONE (SN)	NECESSARY	\$140.00	\$60.00
			\$288.00	\$80.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$480.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FENDER SITE COVER - R/H AND EXHAUST ASSY		\$520.00	\$300.00
			\$1,080.00	\$300.00
GRAND TOTAL			\$12,267.00	\$4,050.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,200.00
Report Ref No: CS/INC24110010/Unh3m4				

TOTAL FOR SPARE PARTS: \$11,187.00 \$ 3,750.20
TOTAL FOR LABOUR : \$ 1,080.00 \$ 300.00
TOTAL REPAIR COST: \$12,267.00 \$ 4,050.20

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.