7/9/24, 2:57 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24060245/EVP3M4

Date: 09/07/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MQ004607 **Claimant Vehicle**

SH9070X **Insured Vehicle No:** GBD9497X No:

Date of Loss: 22/06/2024 Nature of Claim: ΤP Claim No: M2403486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9070X

Make & Model: BYD E6 (ME-2), (A) Engine No: HIDDEN

Reg. Date: 31/05/2022 (Man. Year: 2022) Chassis No: LC0CE4DC6N0008773

Colour: Blue Odometer: 171688 km

Engine Capacity: 0 сс Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Footbrake (Serviceable): Yes Yes **Engine Modification:** Pre-accident Condition: Good Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17 Front Left Side: Rear Left Side: **DURATURN 6 mm** DURATURN 6 mm Front Right Side: DURATURN 6 mm Rear Right Side: DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,575.00	2,575.00	0.00	0.00
Miscellaneous Items		12.00	12.00	0.00	0.00
Labour		2,030.00	1,200.00	830.00	40.89
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,617.00	3,787.00	830.00	17.98
	+ GST 9.00/9.00% (S\$)	415.53	340.83	74.70	17.98
	Nett Amount (S\$)	5,032.53	4,127.83	904.70	17.98

INSPECTION

ComfortDelGro Engineering Pte Ltd (Loyang) Date of Assignment: 24/06/2024 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 25/06/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

CHEN TSUE YEE VERON CHEN Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/9/24, 2:57 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2024)

Parts: M1-MPV BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH9070X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL RH	Dented	2,950.00 FL	*2,950.00 FL
2	1		*REAR DOOR E100% STICKER RH	Necessary	100.00 FS	*100.00 FS
3	1		*REAR DOOR LINE STICKER RH	Necessary	40.00 FS	*40.00 FS
<u>Sup</u>	<u>pleme</u>	entary #1				
4	1		*FRONT DOOR COMFORT STICKER	Necessary	75.00 FS	*75.00 FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	3,165.00	3,165.00
			- List Item Discount on L Ite	ns 20.00/20.00% (S\$)	590.00	590.00
				Total Parts (S\$)	2,575.00	2,575.00
			Report was unsubmitted durin	g this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			,
1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,050.00	400.00
2	SPRAY PAINTING	New	900.00	750.00
3	TRANFER DOOR PARTS	New	80.00	50.00
		Gross Labour Cost (S\$)	2,030.00	1,200.00
	Rep	ort was unsubmitted during this print-out.		

< END OF ESTIMATES >