



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623	Ref: CS3/SMO24110015/Kqh3e2 Date: 05/11/2024 Code: SMO
---	--

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SME 9483A	Veh. Inspected	FBR 4415S
Policy No.	-	Coverage	0
Claim No.	CMTD2403263/AGC	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	01/11/2024

2. Vehicle Details

Make & Model	YAMAHA WR155R MANUAL	C.C	155
Engine No.	G3N6E0001252	Year of Reg.	09/07/2020
Chassis No.	MH3DG3710LK001269	Colour	MULTI COLOUR
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	2.75X21	DUNLOP	6
L/H Front Tyre	2.75X21	DUNLOP	6
R/H Rear Tyre	4.10X21	DUNLOP	7
L/H Rear Tyre	4.10X21	DUNLOP	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

5. General Information

Accident Date	07/10/2024	Inspection Date	01/11/2024 (15:00)
Survey held at	BROTHER MOTORS BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days