



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 1410Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	BENT	\$1,540.00	\$1,540.00
1	REAR TAILGATE EMBLEM	NECESSARY	\$55.00	\$55.00
1	REAR TAILGATE OUTER GARNISH	DENTED	\$245.20	\$245.20
2	REAR TAILGATE REFLECTOR @\$403.50	O/S CUT	\$807.00	\$403.50
1	REAR TAILGATE LOCK	DENTED	\$213.70	\$213.70
1	REAR TAILGATE INNER BOARD	SERVICEABLE	\$228.80	\$0.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$204.20	\$0.00
1	REAR W/SCREEN MLDG	NO SUCH PARTS	\$116.00	\$0.00
1	REAR BUMPER ASSY	BUCKLED	\$812.60	\$812.60
1	REAR BUMPER LAMP RH	CRACKED	\$531.00	\$531.00
1	REAR BUMPER LOWER	CRACKED	\$296.50	\$296.50
1	REAR BUMPER LOWER GARNISH	DENTED	\$126.95	\$126.95
1	REAR BUMPER REINFORCEMENT	CRACKED	\$394.90	\$394.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$785.60	\$0.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	\$235.20	\$0.00
1	REAR BUMPER TOW COVER	DENTED	\$35.00	\$35.00
	<b>LESS 0.00 / 20.00% DISCOUNT</b>		\$0.00	(\$930.87)
			<b>\$6,627.65</b>	<b>\$3,723.48</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	\$60.00	\$40.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	\$300.00	\$200.00
			<b>\$360.00</b>	<b>\$240.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX , CUT & WELD AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$900.00	\$550.00
	TO SPRAY PAINT ON AFFECTED PARTS		\$900.00	\$650.00
	TO REMOVE & REFIX REAR W/SCREEN		\$150.00	\$120.00
	TO TRANSFER TAILGATE MECHANISM		\$100.00	\$60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING		\$40.00	\$20.00
	TO REMOVE & REFIX REVERSE SENSOR		\$80.00	\$50.00
	TO REMOVE & REFIX REAR GARNISHES		\$100.00	\$50.00
	TUFF COAT		\$60.00	\$30.00
			\$2,330.00	\$1,530.00
GRAND TOTAL			\$9,317.65	\$5,493.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,400.00
Report Ref No: CS/TP24110021/Kvh3m4				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.