

ASS. REC. BY:

REF:

TP /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNA 14104

Yr Regn:

061 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Kang

C.C.

1580

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

238158

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMIHK281 EVMA 070447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/55R17

R:

BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

16/9/24

D.O.I.

1/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9 21.30 @ 4400L

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

ump Sum / I.B.I: (\$

TOTAL

Serve You
SMA1410Y

NOT Noted
11/10/2020 @ 440d
Recovery After Rain

Rear tailgate	Qty	Price	Unit
" " emblem	1	1540.00	✓
" " outer garnish	1	55.00	✓
" " reflector x2	2	245.20	✓
" " lock	1	807.00	✓
" " inner board	1	213.70	✓
" " weather strip	1	228.80	x
" " wheel arch mldg	1	204.20	x
" " sealant	1	116.00	x
" bumper Assy	1	60.00	✓
" " lamp RH	1	812.60	✓
" " lower	1	531.00	✓
" " lower garnish	1	296.50	✓
" " reverse sensor	1	126.95	✓
" " reinforcement	1	300.00	✓
" end panel	1	394.90	✓
" " " top garnish	1	785.60	x
" bumper tow cover	1	135.20	x

LKK Auto Consultants hence notify
the Repairer of the following
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Labour

To remove, refit, cut & weld affected parts	900.00	55d ✓
To spray paint on affected parts	900.00	65d ✓
To remove & refit rear wheel arch	150.00	12d ✓
To transfer tailgate mechanism	100.00	6d ✓
Check wiring	40.00	2d ✓
To remove & refit reverse sensor	80.00	5d ✓
To remove & refit rear garnishes	100.00	5d ✓
Tuff Coat	60.00	3d ✓

Acknowledged by Repairer
Signature:
Date: