

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110022/UPA3Q2**Date:** 07/01/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230125506
Claimant Vehicle No :	GBB8964G	Insured Vehicle No :	SNN5869M
Date of Loss:	30/10/2024	Nature of Claim:	TP
		Claim No:	4681029101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB8964G		
Make & Model:	NISSAN CABSTAR, 3.0 5 ABS 2DR 2WD 3.4T (M)	Engine No:	ZD30254650K
Reg. Date:	31/07/2010 (Man. Year: 2010)	Chassis No:	JN1SC2F24Z0801485
Colour:	Silver	Odometer:	206885 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Toyo 6 mm	Rear Left Side:	Nexen 6/6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Nexen 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,086.94	4,381.94	16,705.00	79.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,900.00	2,380.00	3,520.00	59.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,986.94	6,761.94	20,225.00	74.94
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	26,986.94	5,400.00	21,586.94	79.99
+ GST 9.00/9.00% (S\$)	2,428.82	486.00	1,942.82	79.99
Nett Amount (S\$)	29,415.76	5,886.00	23,529.76	79.99
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		6,703.25		

INSPECTION

Date of Assignment:	30/10/2024	
Date Inspected:	30/10/2024	Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN RUBBER	Not Necessary	150.37 FL	*- FL
2	1		*FRONT WIPER PANEL GARNISH	Not Necessary	467.30 FL	*- FL
3	1		*FRONT HEADLAMPS L/R	N/S Not Necessary /O/S Cracked	1,412.40 FL	*484.20 FL
4	1		*FRONT PANEL	Not Necessary	1,634.20 FL	*- FL
5	2		*FRONT CORNER PANEL L/R	Not Necessary	912.80 FL	*- FL
6	1		*FRONT GRILLE	Not Necessary	511.30 FL	*- FL
7	1		*FRONT GRILLE LOGO	Not Necessary	68.20 FL	*- FL
8	1		*FRONT BUMPER	Cut / Deformed	725.40 FL	*725.40 FL
9	2		*FRONT BUMPER BRACKET L/R	Not Necessary	547.20 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP COVER L/R	Not Necessary	70.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	745.20 FL	*- FL
12	1		*CABIN REAR PILLAR RH	Repair	828.10 FL	*- FL
13	1		*TAILGATE	Dented / Bent	1,831.40 FL	*1,688.30 FL
14	1		*TAILGATE NISSAN STICKER	Necessary	158.30 FL	*158.30 FL
15	3		*TAILGATE HINGES	Not Necessary	233.10 FL	*- FL
16	1		*TAILGATE SIDE LOCK RH	Bent	200.10 FL	*150.20 FL
17	1		*REAR SIDE GATE RH	Repair	3,243.00 FL	*- FL
18	5		*REAR SIDE GATE HINGES RH	Not Necessary	43.00 FL	*- FL
19	1		*REAR SIDE GATE LOWER MEMBER RH	Repair	823.10 FL	*- FL
20	1		*TAIL LAMP RH	Cracked	412.10 FL	*210.90 FL
21	1		*END PANEL	Dented / Bent	721.40 FL	*645.20 FL
22	1		*END PANEL SIDE BRACKET RH	Bent	141.30 FL	*141.30 FL
23	2		*END PANEL SIDE BRACKET RUBBER STOPPER RH	Cut	100.00 FL	*50.00 FL
24	1		*REAR NUMBER PLATE BRACKET	Bent	124.30 FL	*124.30 FL
25	1		*REAR NUMBER PLATE LAMP	Not Necessary	68.10 FL	*- FL
26	1		*REAR CHASSIS FRAME RH	Repair	1,443.10 FL	*- FL
27	1		*FOOR PANEL	Repair	2,015.20 FL	*- FL
28	1		*SPARE TYRE BRACKET	Not Necessary	284.50 FL	*- FL
29	1		*SPARE TYRE LOCK BRACKET	Not Necessary	314.60 FL	*- FL
30	1		*REAR EXHAUST MUFFLER	Repair	845.60 FL	*- FL
31	1		*REAR EXHAUST MUFFLER BRACKET	Cracked / Torn	188.60 FL	*68.50 FL
32	1		*FRONT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
34	1		*FRONT NUMBER PLATE	Bent	700.00 FS	*30.00 FS
35	1		*SET REVERSE SENSOR	Not fitted	280.00 FS	*- FS
36	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
37	1		*REAR LOWER STEP BAR	Bent	700.00 FS	*300.00 FS
38	1		*TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*10.00 FS
39	1		*TAILGATE 13 PAX STICKER	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,213.27	4,826.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,126.33	444.66
Total Parts (\$\$)	21,086.94	4,381.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT WINDSCREEN	New	150.00	0.00
2	TO CHECK FRONT WIRING & HEADLAMP LEVELING }	New	60.00	30.00
3	TO CHECK REAR WIRING }	New	50.00	0.00
4	TO REPLACE REAR REVERSE SENSOR	New	120.00	0.00
5	TO REPLACE ,STRAIGHTEN AND ALIGN BOTH REAR CHASSIS MEMBERS	New	1,200.00	400.00
6	TO PROVIDE LABOUR WORKMANSHIP	New	2,000.00	900.00
7	TO SPRAY PAINT ON AFFECTED PANELS	New	2,000.00	1,000.00
8	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	120.00	0.00
9	RUST PROOFING	New	200.00	50.00
Gross Labour Cost (\$\$)			5,900.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >