



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMZ 1429A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER, FRONT BUMPER	BUCKLED/CRACKED	\$653.31	\$653.31
1	ABSORBER, FRONT BUMPER ENERGY	SERVICEABLE	\$100.91	\$0.00
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	TO REPAIR SEE LABOUR	\$902.16	\$0.00
1	SUPPORT, FRONT BUMPER SIDE, RH	SERVICEABLE	\$100.49	\$0.00
1	SUPPORT, RADIATOR, UPPER RH	SERVICEABLE	\$99.33	\$0.00
1	MOULDING, FRONT BUMPER SIDE, RH	CUT	\$120.86	\$120.86
1	COVER, FRONT BUMPER HOLE, RH	SERVICEABLE	\$38.22	\$0.00
1	GRILLE SUB-ASSY, RADIATOR	SERVICEABLE	\$532.88	\$0.00
1	GRILLE, RADIATOR, LOWER NO.1	SERVICEABLE	\$224.70	\$0.00
1	JAR ASSY, WINDSHIELD WASHER	SERVICEABLE	\$276.15	\$0.00
1	WHEEL, DISC	DENTED	\$2,554.70	\$2,554.70
1	ABSORBER ASSY, SHOCK, FRONT RH	SERVICEABLE	\$596.19	\$0.00
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	SERVICEABLE	\$298.10	\$0.00
1	JOINT ASSY, LOWER BALL, FRONT RH	SERVICEABLE	\$331.80	\$0.00
1	KNUCKLE, STEERING, RH	SERVICEABLE	\$836.64	\$0.00
1	FENDER SUB-ASSY, FRONT RH	TO REPAIR SEE LABOUR	\$1,236.69	\$0.00
1	LINER, FRONT FENDER, RH	SERVICEABLE	\$255.36	\$0.00
1	EMBLEM, SIDE PANEL, RH	NECESSARY	\$68.88	\$68.88
1	UNIT ASSY, HEADLAMP, RH	CUT	\$3,325.56	\$3,325.56
	<b>LESS 25.00% DISCOUNT</b>		(\$3,138.23)	(\$1,680.83)
			<b>\$9,414.70</b>	<b>\$5,042.48</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER CLIP (SN)	NECESSARY	\$65.00	\$60.00
1	FENDER LINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
1	FRT BUMPER SIDE RETAINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
			<b>\$195.00</b>	<b>\$60.00</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$250.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,800.00	\$440.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, FRONT BUMPER AND FENDER SUB-ASSY, FRONT RH		\$2,000.00	\$400.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT		\$220.00	\$60.00
	TO TRANSFER OF REAR FENDER PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
			\$4,990.00	\$920.00
<b>GRAND TOTAL</b>			<b>\$14,599.70</b>	<b>\$6,022.48</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$4,800.00</b>
Report Ref No: CS/FCI24110024/Kvh3m4				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.