



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2501563
3 ANSON ROAD #16-00	INV Date	17/03/2025
SPRINGLEAF TOWER	Reference	CD/CTI24110025/Kma3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	GBL 113X
Insured Veh.	GBJ 7823U
Claim No.	SNM24D206131
Policy No.	DMCVSNW00048432402
Accident Date	30/10/2024
Inspection Date	04/11/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Ref: CD/CTI24110025/Kma3q2 Date: 17/03/2025 Code: CTI
--	---

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	GBJ 7823U	Veh. Inspected	GBL 113X
Policy No.	DMCVSNW00048432402	Coverage	0
Claim No.	SNM24D206131	Excess	\$0.00
Assign From	JACQUELINE TAN	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE VAN TURBO 5DR MT	C.C	2982
Engine No.	1KDB068406	Year of Reg.	24/02/2021
Chassis No.	JTFHT02P500251351	Colour	SILVER
Odometer	87976 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15X8	LONGWAY	9
L/H Front Tyre	195R15X8	LONGWAY	9
R/H Rear Tyre	195R15X8	LONGWAY	9
L/H Rear Tyre	195R15X8	LONGWAY	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND REAR WINDSCREEN SHATTERED.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2024	Inspection Date	04/11/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 113X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS	SHATTERED	\$1,714.00	\$1,191.00
1	REAR TAILGATE	BENT	\$2,703.00	\$2,051.60
1	REAR TAILGATE TOYOTA EMBLEM	NECESSARY	\$75.00	\$75.00
1	REAR TAILGATE CHROME MOULDING	WARPED	\$197.00	\$197.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$395.00	\$0.00
1	REAR TAILGATE LOCK	TO REPAIR SEE LABOUR	\$350.00	\$0.00
1	REAR TAIL LAMP LH	CRACKED	\$450.00	\$450.00
1	REAR TAIL LAMP LOWER COVER LH	DENTED	\$145.00	\$145.00
1	REAR TAIL BRACKET LH	CRACKED	\$60.00	\$60.00
1	REAR BUMPER	BENT	\$659.00	\$599.50
1	REAR BUMPER SIDE BRACKET LH	DISTORTED	\$50.00	\$50.00
1	REAR END PANEL	BENT	\$475.00	\$475.00
1	REAR PANEL LH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,818.25)	(\$1,323.53)
			\$5,454.75	\$3,970.57

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$100.00	\$40.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	\$300.00	\$200.00
1	70KM DECAL (SN)	NECESSARY	\$40.00	\$20.00
1	REAR TAILGATE STRIPE DECAL (SN)	NECESSARY	\$100.00	\$60.00
			\$590.00	\$370.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR TAILGATE LOCK AND REAR PANEL LH.		\$1,200.00	\$800.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR TAIL LAMP LOWER COVER LH ,REAR END PANEL REAR SIDE PANEL LH & ETC		\$1,200.00	\$850.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC		\$120.00	\$50.00
TO TUFF KOTE & UNDERSEAL MATERIALS		\$100.00	\$60.00
TO CHECK WIRING & ELECTRICAL SYSTEM		\$120.00	\$20.00
		\$2,740.00	\$1,780.00
GRAND TOTAL		\$8,784.75	\$6,120.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,900.00
Report Ref No: CD/CTI24110025/Kma3q2			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X



PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X



PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X



PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X



PHOTOGRAPHS FOR VEHICLE NO. : GBL 113X

