

ASS. REC. BY:

REF:

C721 CS/CTI 24110029/knh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKIC 2221C

Yr Regn:

12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

C.C

Wagon

2356

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

183334

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRC1890GC 200740

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/9/24

D.O.I.

4/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Est not ready

19/11/11 Rep & 3850d Calm (Red. \$ 6112.30, 61%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Withheld
21 Days @ 3850/-
Paying After Paint

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SKK 2221C

Acc: 17.9.24

S/N Parts Description

- 1 Front bumper
- 2 Front bumper reinforcement
- 3 Front bumper retainer X 2
- 4 Front bumper side grille LH
- 5 Headlamp LH
- 6 Headlamp lower bracket LH
- 7 Front fender LH
- 8 Front fender inner shield LH
- 9 Front door LH
- 10 Front door mirror LH
- 11 Front door rubber LH
- 12 Front door hinge X 2
- 13 Air duct LH
- 14 Front wheel rim LH

Unit Price Amt

Bumper	\$819	✓
R	\$315.70	X
also	\$80.40	\$160.80 ✓
in	\$130.00	X
my car	\$1,655.00	✓
car	\$74.30	✓
R	\$726.30	✓
in	\$188.50	X
R	\$977.60	X
R	\$864.00	X
in	\$241.00	X
\$122.00	\$244.00	X
car	\$107.40	✓
nd	\$938.70	✓
7442.3		

209

Labour

- 1 To remove and refit damaged parts
- 2 To spray paint on affected parts
- 3 To transfer both LH doors mechanism
- 4 Wheel alignment
- 5 Tuff coat on affected parts
- 6 To realign headlamp and check wiring

\$1,000.00 350/-
\$1,000.00 660/-
na \$200.00 X
\$120.00 60/-
\$150.00 30/-
\$50.00 20/-

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9962.3