



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2504621

INV Date 18/07/2025

Reference CD/LPC24110031/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 2974H
Insured Veh. XD 6285A
Claim No. 24/24/24/VC05/030124
Policy No. Z24VC05026657
Accident Date 02/11/2024
Inspection Date 05/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110031/Kpa3q2(N)	
			Date: 18/07/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 6285A	Veh. Inspected	SLE 2974H
	Policy No.	Z24VC05026657	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030124	Excess (\$)	0.00
	Assign From	ENG HUEY NI	Assign Date	05/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN X-TRAIL (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JN1JANT32Z0002213	Colour	METALLIC BLUE
	Odometer	116310 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60R18	DUNLOP	6 mm
	L/H Front Tyre	225/60R18	DUNLOP	6 mm
	R/H Rear Tyre	225/60R18	DUNLOP	3 mm
	L/H Rear Tyre	225/60R18	DUNLOP	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/11/2024	Inspection Date	05/11/2024
	Survey held at	ELITE AM PTE. LTD. 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST @ WOODLANDS, 757322 WOODLANDS		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 2974H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BENT	1,208.37	1,021.00
2	FRONT BONNET HINGE LH/RH	O/S DISTORTED	173.75	86.87
1	FRONT BONNET INSULATOR CLIP SET	NECESSARY	32.70	32.70
1	FRONT FENDER	BENT	778.04	715.30
1	FRONT FENDER ARC GARNISH	CUT	218.55	218.55
1	FRONT FENDER INNER SHIELD	SERVICEABLE	362.10	-
1	FRONT FENDER INNER SHIELD CLIP SET	NOT NECESSARY	32.70	-
1	FENDER BRACKET	TO REPAIR SEE LABOUR	61.78	-
1	FENDER PROTECTOR	SERVICEABLE	87.03	-
1	FRONT HEADLAMP RH	MOUNTING CRACKED	3,121.43	2,689.50
1	FRONT HEADLAMP BRACKET RH	TO REPAIR SEE LABOUR	87.20	-
1	WHEELHOUSE RH	TO REPAIR SEE LABOUR	282.96	-
1	WHEELHOUSE UPPER PANEL RH	TO REPAIR SEE LABOUR	248.19	-
1	FRONT WHEEL BEARING	NECESSARY	324.71	324.71
1	FRONT ABSORBER	BENT	454.09	454.09
1	RIM	DENTED	1,691.57	1,434.50
	LESS 30% DISCOUNT		-2,749.55	-2,093.17
			6,415.62	4,884.05
	<u>SPECIAL NETT ITEMS</u>			
1	WHEELHOUSE SEALANT (SN)	NOT NECESSARY	50.00	-
1	TIRE (SN)	SERVICEABLE	280.00	-
			330.00	-
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING FRONT FRAME MEMBERS, FRONT PILLAR. TO REMOVE AND REFIT ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FENDER BRACKET,FRONT HEADLAMP BRACKET RH,WHEELHOUSE RH AND WHEELHOUSE UPPER PANEL RH.		600.00	450.00

Report Ref No. CD/LPC24110031/Kpa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		800.00	600.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		250.00	140.00
	COMPUTERISED WHEEL ALIGNMENT.		80.00	60.00
			1,730.00	1,250.00
GRAND TOTAL			8,475.62	6,134.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CD/LPC24110031/Kpa3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H



PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H



PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H



PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H



PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 2974H

