



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2500404

INV Date 16/01/2025

Reference CD/LPC24110032/Rma3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 229Y
Insured Veh. YP 686R
Claim No. 24/24/24/VC05/030115
Policy No. Z24VC05025534
Accident Date 31/10/2024
Inspection Date 04/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24110032/Rma3q2
300 BEACH ROAD	Date:	16/01/2025
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YP 686R	Veh. Inspected	SHC 229Y
Policy No.	Z24VC05025534	Coverage	0
Claim No.	24/24/24/VC05/030115	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	02/11/2024

2. Vehicle Details

Make & Model	HYUNDAI AE IONIQ HEV FL 1.6 DCT	C.C	1580
Engine No.	G4LEKU386069	Year of Reg.	14/11/2019
Chassis No.	KMHC851CVLU183130	Colour	YELLOW
Odometer	673301 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	TRIANGLE	6
L/H Front Tyre	195/65 R15	TRIANGLE	6
R/H Rear Tyre	195/65 R15	TRIANGLE	6
L/H Rear Tyre	195/65 R15	TRIANGLE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/10/2024	Inspection Date	04/11/2024
Survey held at	31 CORPORATION ROAD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 229Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT	\$430.90	\$430.90
1	FRONT BUMPER CENTER UPPER MOULDING	CUT	\$284.90	\$284.90
1	FRONT BUMPER RADIATOR GRILLE	CUT	\$708.90	\$708.90
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$186.90	\$0.00
1	FRONT BUMPER LOWER GRILLE CENTER MOULDING	NOT NECESSARY	\$44.00	\$0.00
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	\$22.10	\$0.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	\$28.00	\$0.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	\$28.00	\$0.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	\$1,075.10	\$0.00
1	FRONT BUMPER REINFORCEMENT SPONGE	SERVICEABLE	\$86.90	\$0.00
1	FRONT BUMPER TOP SEAL	NOT NECESSARY	\$29.40	\$0.00
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	\$48.30	\$0.00
1	FRONT BUMPER TOW CAP	NOT NECESSARY	\$15.40	\$0.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	\$949.30	\$0.00
	LESS 20.00% DISCOUNT		(\$787.62)	(\$284.94)
			\$3,150.48	\$1,139.76
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$55.00	\$30.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT NUMBER PLATE & FRAME (SN)	CRACKED	\$80.00	\$35.00
1	SUNDRIES (SN)	NECESSARY	\$60.00	\$20.00
			\$255.00	\$85.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	STRAIGHT AND PANEL BEAT ACCIDENT AREA		\$1,000.00	\$400.00
	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM		\$180.00	\$80.00
	R&R RADIATOR INNER & RADIATOR INVERTER & A/C CONDENSER	NOT NECESSARY	\$150.00	\$0.00
	VACUUM & TOP UP AIR COND GAS R-134A	NOT NECESSARY	\$150.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	RESPRAY FRONT BUMPER	NOT NECESSARY	\$250.00	\$200.00
	RESPRAY FRONT BUMPER CENTER UPPER MOULDING		\$200.00	\$200.00
	RESPRAY FRONT BUMPER LOWER GRILLE CENTER MOULDING		\$150.00	\$0.00
			\$2,080.00	\$880.00
GRAND TOTAL			\$5,485.48	\$2,104.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,700.00
Report Ref No: CD/LPC24110032/Rma3q2				


MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y




PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y




PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y





PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y



PHOTOGRAPHS FOR VEHICLE NO. : SHC 229Y

