

REF:

ASSIGNMENT

From:

Date:

Estim. No.:

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No:at W/O km/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vcl:

(Policy Condition)

Remarks: Vehicle had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Material Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP INC

MV:

PV:

Nett:

Veh No:

SNJ6689E

Yr Regn:

2024 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

C.D.

1580

Colour:

Grey

Sp. Reading:

5137

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHLN41JVRU109776

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Keenho

Front

R/Bal.

06

mm

Rear

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

04/11/24

Survey held at

Ryder

Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

COE Expiry:

Estimate given during: Yes (✓)
1st Survey: No ()

1591

Date/Time, File Pass to?

☐ : Prelim. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Addl Fee:

☐ : Site Insp (\$

: Interview (\$

: Tech. Insp (\$

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others

Report Form:

Main Form / P.P. Form