

Vern.

ESTIMATE OF REPAIR

Veh# : SNJ6689E

Model: HYUNDAI AVANTE HEV

Accident Date : 31/10/2024

8/7/2024

Location : WOODLAND SQUARE

3P: SNR3214U (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Front sport rim Rh <i>at</i>	1,237.00	<i>700 (SN)</i>	
2	1pc	Front tyre Rh <i>new</i>		300.00	<i>x</i>
3	1pc	Front shock absorber Rh <i>3rd</i>	497.00	<i>+</i>	
4	1pc	Front shock absorber mounting Rh <i>2nd</i>	76.40	<i>+</i>	
5	1pc	Front lower arm Rh <i>Best</i>	475.00	<i>2</i>	
6	1pc	Front knuckle arm Rh <i>new</i>	508.00	<i>+</i>	
7	1pc	Front knuckle arm bearing Rh <i>Brand</i>	665.00	<i>445</i>	
8	1pc	Front stabiliser bar linkage Rh <i>new</i>	104.30	<i>x</i>	
9	1pc	Front support panel <i>new</i>	1,310.20	<i>x</i>	
10	1pc	Front support panel top garnish cover <i>new</i>	130.00	<i>+</i>	
11	1pc	Front support panel top garnish cover clips <i>new</i>		40.00	<i>+</i>
12	1pc	Front headlamp Rh <i>Cracked</i>	3,309.00	<i>✓</i>	
13	1pcs	Front headlamp holder bracket Rh <i>Cracked</i>	179.80	<i>54</i>	
14	1 pc	Front grille <i>new</i>	1,496.60	<i>+</i>	
15	1 pc	Front bumper <i>tom</i>	807.00	<i>595</i>	
16	1 pc	Front bumper top garnish <i>Repair</i>	103.40	<i>+</i>	
17	1 pc	Front bumper top garnish bracket <i>new</i>	135.60	<i>+</i>	
18	1 pc	Front bumper inner sponge <i>cracked</i>	157.10	<i>✓</i>	
19	1 pc	Front bumper side retainer RH <i>new</i>	78.00	<i>x</i>	
20	1 pc	Front bumper lower grille <i>new</i>	153.30	<i>x</i>	
21	1 pc	Front bumper lower lid garnish <i>new</i>	102.70	<i>+</i>	
22	1 pc	Front bumper lower chrome moulding - centre <i>new</i>	161.70	<i>+</i>	
23	2 pcs	Front bumper lower chrome moulding R/L <i>new</i>	204.40	<i>+</i>	
24	2 pcs	Front bumper foglamp chrome cover R/L <i>new</i>	328.40	<i>x</i>	
25	1 pc	Front bumper logo <i>new</i>	110.00	<i>60</i>	
26	1 pc	Front bumper foglamp cover air duct garnish R <i>new</i>	140.50	<i>x</i>	
27	1 pc	Front bumper foglamp cover air duct cover R <i>new</i>	130.00	<i>85</i>	
28	1 pc	Front bumper lower reinforcement <i>new</i>	102.70	<i>+</i>	
29	1 set	Front bumper clips <i>new</i>		80.00	<i>30</i>
30	1 pc	Front fender Rh <i>new</i>	repair	<i>x</i>	
31	1 pc	Front fender Rh inner shield <i>tom</i>	149.20	<i>✓</i>	
		Sub Total:	12,852.30	420.00	0.00
			20%	0%	0%
		After Less %:	10,281.84	420.00	0.00

5329.30

5 x 730

4263.44

		Labour	
1		To remove & refix accident damaged parts & realign accident affected area.	1,000.00 300
2		To spray paint on accident affected area.	800.00 200
3		To remove & refix air-con condenser, hose & refill gas.	120.00 x
4		To remove & refix radiator, fan assy & other attachment parts.	80.00 x
5		To remove & refix front under carriage suspension.	200.00 150
6		To computerise wheel alignment.	120.00 80
7		To check wiring, layout & renew damaged parts.	120.00 30
8		To diagnosis & reset after work.	300.00 x
		Sub Total:	2,740.00
		Total:	13,441.84
		After less 20%	10,753.47

Chan

760

Adrian
1/s 04/11/24.

050 w/s.

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



Total: 5753.44

1/s : 4.6K

4.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: