



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBW 7361S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH - HAND GUARD	GRAZED	109.89	109.89
1	EXHAUST MUFFLER	TO REPAIR SEE LABOUR	981.00	-
1	REAR TYRE SPLASH GUARD	DAMAGED	98.10	98.10
	LESS 10% DISCOUNT		-	-20.79
			1,188.99	187.20
<u>SPECIAL NETT ITEMS</u>				
1	STEEERING CONE & BEARING (SN)	NOT NECESSARY	130.00	-
1	CRASH BAR (SN)	BENT/CUT	824.04	750.00
1	CRASH BAR SLIDERS (SN)	CUT	156.96	120.00
1	REAR TOP BOX (SN)	CUT	353.16	353.16
			1,464.16	1,223.16
<u>LABOUR</u>				
	FRONT FORK ALIGNMENT.	NOT NECESSARY	230.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	130.00	-
	FRAME ALIGNMENT.	NOT NECESSARY	210.00	-
	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS \$100 PER DAYS X 4 DAYS. INCLUSIVE OF THE REPAIR OF EXHAUST MUFFLER.		400.00	280.00
			970.00	280.00
GRAND TOTAL			3,623.15	1,690.36
RECOMMENDED COST OF REPAIRS				1,690.36

Report Ref No. CS/CTI24110035/Unh3m4(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.