

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110041/UQP3E2
Date: 15/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003657200
Claimant Vehicle No :	XD7177Y	Insured Vehicle No :	SNB4160T
Date of Loss:	27/10/2024	Nature of Claim:	TP
		Claim No:	378138

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD7177Y	Engine No:	6M70457033
Make & Model:	MITSUBISHI FV51JJD4RDEA, 12.9 D (M)	Chassis No:	FV51JJA10133
Reg. Date:	28/06/2013 (Man. Year: 2013)	Odometer:	804686 km
Colour:	White/Blue		
Engine Capacity:	12882 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,450.00	2,156.50	11,293.50	83.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	870.00	5,260.00	85.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,580.00	3,026.50	16,553.50	84.54
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	19,580.00	2,400.00	17,180.00	87.74
+ GST 9.00/9.00% (S\$)	1,762.20	216.00	1,546.20	87.74
Nett Amount (S\$)	21,342.20	2,616.00	18,726.20	87.74

INSPECTION

Date of Assignment:	05/11/2024	
Date Inspected:	05/11/2024	Inspected At: HUP LIAN HUAT ENGINEERING WORKS (HQ) 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, SINGAPORE 539278
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jan 2025)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7177Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP ASSY - LH / RH	N/S Cracked	760.00 F	*292.00 FN
2	2		*TAIL LAMP BRACKET - LH / RH	Repair	760.00 F	*- FN
3	1		*REAR MUDGUARD - LH	Not Necessary	1,200.00 F	*- FN
4	2		*REAR MUDGUARD BRACKET - LH / RH	Not Necessary	1,160.00 F	*- FN
5	2		*REAR MUDGUARD RUBBER - LH / RH	Not Necessary	400.00 F	*- FN
6	2		*REAR CHASSIS	Repair	5,600.00 F	*- FN
7	1		*REAR CHASSIS HOOK	Repair	580.00 F	*- FN
8	1		*SET REAR CROSSMEMBER	Distorted	2,000.00 FS	*1,600.00 FS
9	1		*REAR LICENSE LAMP (2PCS)	Cracked (1Pc Only)	360.00 F	*180.00 FN
10	2		*REAR LICENSE LAMP BRACKET	Repair	300.00 F	*- FN
11	1		*REAR SPOOTLIGHT - LH	Cracked	250.00 F	*250.00 FN
12	1		*REAR NUMBER PLATE	Bent	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	13,450.00	2,337.00
- Nett Item Discount on N Items 0.00/25.00% (\$)	0.00	180.50
Total Parts (\$)	13,450.00	2,156.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & RENEW TAIL LAMP & CHECK WIRING & REFOCUS ALL LIGHT	New	580.00	20.00
2	LABOUR TO REMOVE & REFIX REAR CHASSIS, REAR CROSSMEMBER }	New	1,600.00	500.00
3	LABOUR CHARGE TO DISMANTLE & CUT & WELDING RH REAR MUDGUARD BRACKET, REAR WHEEL MUDGUARD, SIDEGUARD & BRACKET }	New	1,500.00	0.00
4	TO RUST PROOFING ON AFFECTED AREA	New	950.00	0.00
5	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	1,500.00	350.00
			Gross Labour Cost (\$\$)	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >