

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 09 Dec 2024

**Preliminary Advice**

Insured Vehicle No : SNB4160T  
TP Vehicle No : XD7177Y  
Make : MITSUBISHI FV51JJD4RDEA  
Date of Inspection : 05/11/2024  
Inspection At : HUP LIAN HUAT ENGINEERING WORKS (HQ)  
38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE,  
SINGAPORE 539278  
Accident Date : 27/10/2024  
Assignment Date : 05/11/2024  
Est. Duration of Repair : 2

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,580.00
Revised Amount	:S\$	3,026.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,026.50
Lump Sum Repair	:S\$	2,400.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	27,623.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,377.00

**Remarks**

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair
  
- The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.