



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GX 72H

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN GLASS (N)	CRACKED	\$1,374.00	\$1,374.00
1	FRONT WINDSCREEN RUBBER (N)	NECESSARY	\$197.20	\$148.20
1	FRONT WIPER PANEL GARNISH (N)	DENTED/WARPED	\$437.20	\$437.20
1	FRONT WIPER MOTOR (N)	DAMAGED/JAMMED	\$712.80	\$600.80
2	FRONT WIPER ARM (N)	CRACKED/BENT	\$490.40	\$320.00
1	FRONT BODY PANEL (N)	TO REPAIR SEE LABOUR	\$1,583.70	\$0.00
2	FRONT WIPER ARM COVER (N)	MISSING	\$57.20	\$57.20
2	FRONT WIPER BLADE (N)	O/S MISSING	\$112.20	\$56.10
2	FRONT SIDE MIRROR (N)	N/S SERVICEABLE / O/S BROKEN	\$379.00	\$189.50
2	FRONT SIDE MIRROR STAY (N)	N/S SERVICEABLE / O/S BENT	\$875.00	\$437.50
1	FRONT SIDE MIRROR ROUND (N)	DAMAGED	\$89.40	\$89.40
2	FRONT SIDE MIRROR STAY COVER (N)	CRACKED	\$454.60	\$454.60
1	FRONT SIDE MIRROR ROUND STAY COVER (N)	NOT NECESSARY	\$109.80	\$0.00
	LESS 10.00%		(\$687.25)	(\$416.45)
			\$6,185.25	\$3,748.05

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	FRONT STICKER "FLAMMABLE GAS" (SN)	NECESSARY	\$80.00	\$50.00
			\$210.00	\$50.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING	NOT NECESSARY	\$80.00	\$30.00
	TO REMOVE & REFIT DASHBOARD		\$500.00	\$200.00
	TO REMOVE & REFIT FRONT WINDSCREEN GLASS		\$180.00	\$60.00
	TO APPLY UNDERCOATING		\$150.00	\$0.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BODY PANEL		\$1,500.00	\$520.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON THE AFFECTED AREAS		\$1,200.00	\$400.00
			\$3,610.00	\$1,210.00
GRAND TOTAL			\$10,005.25	\$5,008.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,000.00
Report Ref No: CS/SMO24110046/Unp3e2				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.